

May 01, 2019

Don Whisman  
Principal  
Franklin Elementary School  
4481 Copeland Avenue  
San Diego, CA 92116

Subject: Franklin ES School Drinking Water Project Closeout

Dear Mr. Whisman:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Franklin ES campus.

As part of a district wide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Franklin Elementary School for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Franklin ES campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto  
Manager, Facilities Planning



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Nurse Office - HLC1, North Wall	DWO-113-001	Faucet	1.30		
2	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Office - MOFS, East Wall	DWO-113-002	Faucet	6.83	FLTR	0.09
3	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Food Services/Kitchen - FSK1, East Wall	DWO-113-003	Faucet	1.64		
4	5 Classrooms 14-18 - Franklin_04-05 Building Exterior, South Wall Left Side	DWO-113-004	Bottle Filler	<5		
5	5 Classrooms 14-18 - Franklin_04-05 Building Exterior, South Wall Right Side	DWO-113-005	Bottle Filler	1.36		
6	5 Classrooms 14-18 - Franklin_04-05 Classroom - 14, West Wall	DWO-113-006	Drinking Fountain Bubblers	9.64	FLTR	ND
7	5 Classrooms 14-18 - Franklin_04-05 Classroom - 15, West Wall	DWO-113-007	Drinking Fountain Bubblers	1.86		
8	5 Classrooms 14-18 - Franklin_04-05 Classroom - 16, West Wall	DWO-113-008	Drinking Fountain Bubblers	1.99		
9	5 Classrooms 14-18 - Franklin_04-05 Classroom - 17, West Wall	DWO-113-009	Drinking Fountain Bubblers	1.42		
10	5 Classrooms 14-18 - Franklin_04-05 Classroom - 17, North Wall	DWO-113-010	Drinking Fountain Bubblers	0.74		
11	5 Classrooms 14-18 - Franklin_04-05 Classroom - 18, North Wall	DWO-113-011	Drinking Fountain Bubblers	3.04		
12	5 Classrooms 14-18 - Franklin_04-05 Classroom - 18, West Wall	DWO-113-012	Drinking Fountain Bubblers	<5		
13	Portable B11/B12 - Franklin Classroom - B12, North Wall	DWO-113-013	Drinking Fountain Bubblers	0.80		
14	Portable B11/B12 - Franklin Classroom - B11, North Wall	DWO-113-014	Drinking Fountain Bubblers	0.71		
15	Portable B10/B11 - Franklin Classroom - B10, North Wall	DWO-113-015	Drinking Fountain Bubblers	1.74		
16	Portable B07/B08 - Franklin Classroom - B07, West Wall	DWO-113-016	Drinking Fountain Bubblers	0.83		



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Portable B07/B08 - Franklin Classroom - B08, West Wall	DWO-113-017	Drinking Fountain Bubblers	1.14		
18	Portable B08/B09 - Franklin Classroom - B09, West Wall	DWO-113-018	Drinking Fountain Bubblers	5.15	RRC	1.38
19	7 Library - Franklin_06-07 Faculty Workroom - WRK1, South Wall	DWO-113-019	Faucet	0.61		
20	2 Classrooms 7-12 - Franklin_02-02 Common Area/Hallway - HAL1, East Wall Left Side	DWO-113-020	Drinking Fountain Bubblers	<5		
21	2 Classrooms 7-12 - Franklin_02-02 Common Area/Hallway - HAL1, East Wall Right Side	DWO-113-021	Drinking Fountain Bubblers	1.64		
22	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Left Side	DWO-113-022	Drinking Fountain Bubblers	0.97		
23	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Middle	DWO-113-023	Drinking Fountain Bubblers	1.30		
24	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Right Side	DWO-113-024	Drinking Fountain Bubblers	2.24		
25	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Left Side	DWO-113-025	Drinking Fountain Bubblers	4.46		
26	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Middle	DWO-113-026	Drinking Fountain Bubblers	1.69		
27	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Right Side	DWO-113-027	Drinking Fountain Bubblers	1.44		
28	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Southeast End of Hall Left	DWO-113-028	Drinking Fountain Bubblers	<5		
29	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Southeast End of Hall Right	DWO-113-029	Drinking Fountain Bubblers	1.49		
30	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Northeast End of Hall Left	DWO-113-030	Drinking Fountain Bubblers	1.80		
31	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Northeast End of Hall Right	DWO-113-031	Drinking Fountain Bubblers	1.51		
32	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, East Wall Left Side	DWO-113-032	Drinking Fountain Bubblers	0.95		



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Closeout Report

Date of Report: 05/01/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33 1 Classrooms 1-6 - Franklin_01-01 Building Exterior, East Wall Right Side	DWO-113-033	Drinking Fountain Bubbler	1.50		
34 1 Classrooms 1-6 - Franklin_01-01 Faculty Workroom - WRK6, West Wall	DWO-113-034	Drinking Fountain Bubbler	2.04		
35 3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Office - WAIT, East Wall	DWO-113-035	Drinking Fountain Bubbler	4.43		

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.