

Glenn Boogren
Operations Division
Safety, Training, Personnel and
Environmental Compliance Manager
P: 858/260-5487
F: 858/627-7521
gboogren@sandi.net

June 15, 2017

Ms. Amanda Hammond-Williams Principal Birney Elementary School 4345 Campus Avenue San Diego, CA 92103

Subject: Update on Water Quality Investigation & Release of Buildings for Normal Use

Dear Ms. Hammond-Williams:

The following information is provided as an update on the ongoing water quality investigation and remediation work at Birney Elementary school. After a review of water sampling results provided by the City of San Diego and Environmatrix, an independent accredit laboratory, the district's Physical Plant Operations experts have recommended a return to normal operations at the Cafeteria, the 800 Building, and the Kindergarten classrooms.

On May 2nd the city's Public Utilities staff collected five water samples from your school and analyzed them for the presence of lead. The result produced by the sample drawn at an exterior fountain in the cafeteria building indicated lead in the water exceeded the action levels established by the State Water Resources Control Board via the Department of Drinking Water. Upon receipt of the results report, plumbers were quickly dispatched to secure the water to all fountains on campus and to provide bottled water and water drinking stations to the campus.

District plumbing staff conducted remediation work including the replacement of piping, valves, fittings and associated plumbing parts. Ultimately new plumbing was run from the front of school to feed all water outlets in the auditorium.

During the course of the investigation and remediation activities in an around the cafeteria, additional samples were taken to identify and isolate potential sources of the elevated lead levels. Upon completion of the remediation work in the cafeteria, the city and district safety office staff returned to resample the area previously identified as having elevated levels of lead as well as other areas in these buildings.

Post remediation sample results for the cafeteria building indicate that the remediation activities were effective. Additional sampling conducted in the kindergarten & 800 buildings were well below the action level of 15 parts per billion. For these reasons, district staff recommend a return to normal operations in these buildings. The results from samples taken in the buildings proposed for release to normal activities are detailed in the attached sample log.

We continue to investigate the plumbing systems for the 200, 300, & portable classrooms and are therefore recommending that these buildings remain on bottled water until remediation activities occur and sampling results indicate that lead levels have decreased.

If you have any questions or concerns regarding this please contact me.

Sincerely,

Glenn C. Boogren

Manager; Safety, Training, Personnel, & Environmental Compliance

Birney Elementary Campus Water Sampling Data									
Location	Sample Date	Test -Results	Ву	Notes					
Cafe NE Exterior hose bibb	12-May	15	In house/Hach Colorimeter	Investigatory field samples					
Cafe NE Exterior hose bibb	12-May	29	In house/Enviromatrix	Investigatory samples					
Cafe NE Exterior hose bibb	24-May	9	In house/Enviromatrix	No further action - Hose bibb removed, new install at fountain					
Café near lunch court. exterior wall mount-									
upper right fountain	2-May	19	City	Intitial City Sampling					
Café near lunch court. exterior wall mount-									
upper right fountain	17-May	26	In house/Hach Colorimeter	Investigatory field samples					
Café near lunch court. exterior wall mount-	1475-1475 AV		50 N (1995) at 10	×					
upper right fountain	17-May	98	In house/Enviromatrix	Investigatory samples					
Café near lunch court. exterior wall mount-		~							
upper right fountain	22-May	6	In house/Enviromatrix	Investigatory samples					
Café near lunch court. exterior wall mount- upper right fountain	22 May	4 E	In house/Hash Colorimator	Investigator field assesses					
Café near lunch court, exterior wall mount-	22-May	<5	In house/Hach Colorimeter	Investigatory field samples					
upper right fountain	2-Jun	<5 (VERBAL)	City	City CLEARANCE - no further action					
apper righterountain	2 3011	(3 (VENDAL)	City						
Witch on Sink/oridallo (Doon)	12.14-		to be seen filled by Collection to	Initial draw plus conscutive samples (250 ML) investigatory					
Kitchen Sink(middle/Prep) Kitchen Sink(middle/Prep)	12-May	<5	In house/Hach Colorimeter	samples					
Kitchen Sink(middle/Prep) Kitchen Sink(middle/Prep)	12-May	<5 <5	In house/Hach Colorimeter In house/Hach Colorimeter	Second conscutive samples (250 ML) investigatory samples					
Kitchen Sink(middle/Prep)	12-May 12-May	<5 <5	In house/Hach Colorimeter	Third conscutive samples (250 ML) investigatory samples					
Kitchen Sink(middle/Prep)	22-May	5	In house/Hach Colorimeter	Fourth conscutive samples (250 ML) investigatory samples Investigatory field samples					
Kitchen Sink(middle/Prep)	24-May	6	In house/Enviromatrix	No further action					

Kitchen sink 3 compartment	18-May	5	In house/Hach Colorimeter	Investigatory field samples					
Kitchen sink 3 compartment	22-May	7 8	In house/Hach Colorimeter	Investigatory field samples					
Kitchen sink 3 compartment	24-May	****	In house/Enviromatrix	No further action - sink used for dish washing					
Kitchen sink Left/SE corner	22-May	<5	In house/Hach Colorimeter	Investigatory field samples					
Kitchen sink Left/SE corner	24-May	5	In house/Enviromatrix	No further action					
Preschool Court Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room 821 Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room 823 Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room 825 Fountain	24-May	5	In house/Enviromatrix	No further action					
Room 826 Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room 828 Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room 830 Fountain	24-May	ND	In house/Enviromatrix	No further action					
Room K-1 class fountain-center bubbler	2-May	<5	City	No further action					
Room K-2 fountain	24-May	5	In house/Enviromatrix	Nofurther action					

ND = Not Detected

BLR = Below Reportable Limits

Enviromatrix & EMC Labs are certified independent laboratory used for sample analysis colorimeter used is a Hach Colorimeter II Filter Photometer



Environmental Monitoring and Technical Services 2392 Kincaid Road MS 45A. San Diego, CA 92101 Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services Lead School Testing Report Date: 6/20/17

San Diego Unified School District Birney Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1176173	06/02/17	06:10 AM	SAMPLE 1 1ST FOLLOW-UP	3710020-AJJ-A	< 5	ug/L

Source Description

SAMPLE 1 After Remediation - Cafeteria, Wall mounted exterior (North of Bldg), facing lunch court, two single bubbler fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L

Tom Burger Associate Chemist