



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Keiller Leadership Academy

Report Type: Progress Report

Date of Report: 04/11/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	4 Admin/Supply - Keiller_01-04 Lounge, south wall	DWO-365-001	Faucet	0.90		
2	4 Admin/Supply - Keiller_01-04 Nurse Cot Rm, west wall	DWO-365-002	Faucet	0.81		
3	4 Admin/Supply - Keiller_01-04 Building Exterior, west side of bldg, left fixture	DWO-365-003	Drinking Fountain Bubblers	0.55		
4	4 Admin/Supply - Keiller_01-04 Building Exterior, west side of bldg, right fixture	DWO-365-004	Drinking Fountain Bubblers	0.39		
5	Classrooms 5-8 - Keiller Building Exterior, east side of bldg, left fixture	DWO-365-005	Drinking Fountain Bubblers	1.57		
6	Classrooms 5-8 - Keiller Building Exterior, east side of bldg, right fixture	DWO-365-006	Drinking Fountain Bubblers	<5		
7	Classrooms 5-8 - Keiller Classroom - 05, east wall	DWO-365-007	Drinking Fountain Bubblers	1.44		
8	Classrooms 5-8 - Keiller Classroom - 08, east wall	DWO-365-008	Drinking Fountain Bubblers	2.07		
9	Classrooms 5-8 - Keiller Classroom - 07, west wall	DWO-365-009	Drinking Fountain Bubblers	1.37		
10	6 Gym - Keiller_02-06 Building Exterior, north side, left fixture	DWO-365-010	Drinking Fountain Bubblers	14.59		
11	6 Gym - Keiller_02-06 Building Exterior, north side, right fixture	DWO-365-011	Drinking Fountain Bubblers	2.51		
12	6 Gym - Keiller_02-06 Girls Locker/Shower 29 - LKG29, north wall girls locker	DWO-365-012	Drinking Fountain Bubblers	4.11		
13	6 Gym - Keiller_02-06 Exercise Room - PEA1, north wall	DWO-365-013	Drinking Fountain Bubblers	3.66		
14	6 Gym - Keiller_02-06 Building Exterior, south side, left fixture	DWO-365-014	Drinking Fountain Bubblers	8.14		
15	6 Gym - Keiller_02-06 Building Exterior, south side, right fixture	DWO-365-015	Drinking Fountain Bubblers	6.12		
16	6 Gym - Keiller_02-06 Boys Locker/Shower 28 - LKB28, south wall of boys	DWO-365-016	Drinking Fountain Bubblers	4.39		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Keiller Leadership Academy

Report Type: Progress Report

Date of Report: 04/11/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Portable B25 - Keiller Classroom - B25, west wall	DWO-365-017	Drinking Fountain Bubbler	3.61		
18	Portable B24 - Keiller Classroom - B24, east wall	DWO-365-018	Drinking Fountain Bubbler	6.28		
19	Portable B21 - Keiller Classroom - B21, west wall	DWO-365-019	Drinking Fountain Bubbler	6.54		
20	7 Library - Keiller_03-07 Faculty Workroom (MDF) - L105A, southeast wall	DWO-365-020	Faucet	2.06		
21	Classrooms 9-11 - Keiller Building Exterior, east side, left fixture	DWO-365-021	Drinking Fountain Bubbler	<5		
22	Classrooms 9-11 - Keiller Building Exterior, east side, right fixture	DWO-365-022	Drinking Fountain Bubbler	1.30		
23	8 G&H Classrooms - Keiller_03-08 Building Exterior, east wall, left fixture, lower level	DWO-365-023	Drinking Fountain Bubbler	1.38		
24	8 G&H Classrooms - Keiller_03-08 Building Exterior, east wall, right fixture, lower level	DWO-365-024	Drinking Fountain Bubbler	<5		
25	8 G&H Classrooms - Keiller_03-08 Building Exterior, east wall, left fixture, upper level	DWO-365-025	Drinking Fountain Bubbler	1.45		
26	8 G&H Classrooms - Keiller_03-08 Building Exterior, east wall, right fixture, upper level	DWO-365-026	Drinking Fountain Bubbler	1.43		
27	5 Auditorium/Cafeteria/Kitchen - Keiller_01-05 Building Exterior, north exterior wall, left fixture	DWO-365-027	Drinking Fountain Bubbler	<5		
28	5 Auditorium/Cafeteria/Kitchen - Keiller_01-05 Building Exterior, north exterior wall, right fixture	DWO-365-028	Drinking Fountain Bubbler	1.10		
29	5 Auditorium/Cafeteria/Kitchen - Keiller_01-05 Parents Rm, north wall	DWO-365-029	Faucet	0.85		
30	Classrooms 9-11 - Keiller Classroom - 09, east wall	DWO-365-030	Faucet	10.60		
31	Classrooms 9-11 - Keiller Classroom - 10, east wall	DWO-365-031	Faucet	1.32		

*Action levels and color indication



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Keiller Leadership Academy

Report Type: Progress Report

Date of Report: 04/11/19

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
----------	--------	------	-----------------	----------------	------------------

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

****Clearance actions**

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.