

# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site: IMC

7-Aug-17

Sampler SDUSD-Safety Office

Analyzed by: Enviromatrix Labs 17G0818 IMC

Sample ID	Sample Date	Sample Location	Lead result	Units	Type of Fixture
1	27-Jul	In hallway near door opening to VAPA	ND	ug/l	leftside drinking fountain
2	27-Jul	VAPA area-Inside kitchen break room	ND	ug/l	sink faucet
3	27-Jul	between restrooms near loading dock doors	5	ug/l	drinking fountain
4	27-Jul	VAPA area-Inside room 3	ND	ug/l	sink faucet
5	27-Jul	Bungalow E-Inside SW corner break room	ND	ug/l	sink faucet