



May 29, 2018

Andrew Gergurich
Principal
Angier Elementary
8450 Hurlbut St.
San Diego, CA 92123

Subject: Angier Elementary Drinking Water Project Closeout

Dear Andrew:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Angier Elementary campus.

On January 25, 2018, the district Safety Office sampled all drinking water outlets at Angier Elementary for elevated levels of lead. Safety Office staff first identified all drinking water outlets and tagged them with a blue sticker. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to an accredited local laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Angier Elementary campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Vey", written over a light blue circular stamp.

Darin Vey
Manager (TOC); Safety, Training, Personnel, & Environmental Compliance

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Angier Elementary School					Report Date:	05/18/18
Sampler:	SDUSD - Safety Office						
Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB. Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level Units = ug/L							
Sample ID	Sample Location	Lead Results	Action Taken	Clearance Date	Clearance Result	Type of Fixture	
1	Health Office South wall at sink	1.12				DB	
2	Student Center East wall at sink	4.65				DB	
3	Inside Cafeteria NE-Wall 1 at wall at hand washing trough sink	2.45				DB	
4	Inside Kitchen, E-Wall at two compartment sink	1.78				DB	
5	Inside Kitchen, S-Wall at sink SD 3	10.20	F	5/6/2018	ND	CF	
6	Inside PTO South wall at sink (Rm is next to Cafeteria)	3.90				DB	
7	BLDG RMS 3-8 EXTERIOR Left Trough - RIGHT	ND				DB	
8	BLDG RMS 3-8 EXTERIOR Left Trough - LEFT	ND				DB	
9	BLDG RMS 3-8 EXT, Right Trough - Left Bubbler	ND				DB	
10	BLDG RMS 3-8 EXT, R-Trough, R-Bubbler SD 4	<5				DB	
11	K-1, S-WALL R	2.11				DB	
12	K-1, W-WALL	6.07	F	5/15/2018	ND	DB	
13	K-2, N-Wall, bubbler on R-Side SD 5	<5				DB	
14	KINDER PLAYGROUND W-WALL R-Side	2.31				DB	
15	RM 3, S-WALL R-side	3.51				DB	
16	RM 4, S-WALL, R-Side	3.73				CF	
17	RM 5, S-WALL, R-Side	0.96				DB	
18	RM 6, W-WALL, R-Side	10.80	F	3/3/2018	0.08	DB	
19	RM 7, W-WALL, R-Side	ND				DB	
20	RM 8, W-WALL, R-Side	2.95				DB	
21	Ext, near Rm 9, L-Trough, L-Side SD 1	<5				DB	
22	Ext, near Rm 9, L-Trough, R-Side	0.80				DB	
23	Ext, near Rm 9, R-Trough, L-Side	0.85				DB	
24	Ext, near Rm 9, R-Trough, R-Side	0.63				DB	
25	Ext, near Rm 9, single bubbler	0.82				DB	

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable;

F= Filter; R= Repaired; RM= Removed

SD 1 through SD 5 = Sampled by City of San Diego

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Angier Elementary School					Report Date:	05/18/18
Sampler:	SDUSD - Safety Office						
<p>Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.</p> <p>Green shading = below District & Federal Action Levels</p> <p>Yellow shading = below Federal Action level/Above District Action Level</p> <p>Red Shading = above Federal Action Level</p> <p>Units = ug/L</p>							
Sample ID	Sample Location	Lead Results	Action Taken	Clearance Date	Clearance Result	Type of Fixture	
26	Rm 9, NW Wall, gooseneck (Special Ed Classroom)	3.02				DB	
27	Rm 9, NW Wall, Bubbler (Special Ed Classroom)	1.58				DB	
28	Rm 10, NW Wall, gooseneck (Special Ed Classroom)	5.69	R	3/3/2018	2.4	DB	
29	Rm 10, NW Wall, Bubbler (Special Ed Classroom)	2.12				DB	
30	Rm 11, NW Wall	9.99	F	3/3/2018	0.24	DB	
31	Rm 12, SE Wall, gooseneck (Staff Lounge)	2.73				DB	
32	Rm 12, SE Wall, Bubbler (Staff Lounge)	1.16				DB	
33	Rm 13, SE Wall	1.94				DB	
34	Rm 14, SE Wall	3.43				DB	
35	Rm 15, SE Wall	5.64	F	3/3/2018	0.39	DB	
36	Ext Bubbler, Rm 16, West Wall, Far Left (Left set of 3)	1.27				DB	
37	Ext Bubbler, Rm 16, West Wall, Middle (Left set of 3)	0.98				DB	
38	Ext Bubbler, Rm 16, West Wall, Far Right (Left set of 3)	1.08				DB	
39	Ext Bubbler, Rm 16, West Wall, Far Left (Right set of 3)	1.24				DB	
40	Ext Bubbler, Rm 16, West Wall, Middle (Right set of 3)	1.44				DB	
41	Ext Bubbler, Near Rm 16, West Wall, Far Right (Right set of 3) SD 2	<5				DB	
42	Rm 16, West Wall, Bubbler	2.13				DB	
43	Rm 17, West Wall, Bubbler	2.7				DB	
44	Rm 18, West Wall, Bubbler	12.2	F	3/3/2018	0.65	DB	
45	Rm 19, East Wall, Bubbler	3.49				DB	
46	Rm 20, East Wall, Bubbler	2.51				DB	
47	Rm 21, East Wall, Bubbler	2.66				DB	
48	Rm 22, East Wall, Bubbler	2.38				DB	
49	Rm B23, West Wall, Bubbler	2.33				DB	
50	Rm B24, West Wall, Bubbler	2.01				DB	

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable;

F= Filter; R= Repaired; RM= Removed

SD 1 through SD 5 = Sampled by City of San Diego

