

October 9, 2018

Rudy Akoni  
Principal  
Chesterton Elementary  
7335 Wheathley St.  
San Diego, CA 92111

Subject: Chesterton Elementary Drinking Water Project Closeout

Dear Rudy Akoni:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Chesterton Elementary campus.

As part of a district wide the Safety Office began testing all drinking water outlets at Chesterton Elementary for elevated levels of lead. Safety Office staff first identified all drinking water outlets and tagged them with a blue sticker. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to an accredited local laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Chesterton Elementary campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto  
Manager, Facilities Planning



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Chesterton Elementary

Report Type: Close Out Report

Date of Report: 10/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 10 Admin/Supply - Chesterton_04-10 Workroom, East Wall	DWO-061-001	Faucet	5.24	FLTR	3.49
2 10 Admin/Supply - Chesterton_04-10 Hallway, West Wall	DWO-061-002	Drinking Fountain Bubblers	1.82	INIT	
3 10 Admin/Supply - Chesterton_04-10 Nurse First Aid, West Wall	DWO-061-003	Faucet	1.67	INIT	
4 11 Library/Lounge - Chesterton_04-11 Lounge, West Wall	DWO-061-004	Faucet	6.44	FLTR	3.13
5 11 Library/Lounge - Chesterton_04-11 Workroom, South Wall	DWO-061-005	Faucet	4.53	INIT	
6 9 Auditorium/Cafeteria/Kitchen - Chesterton_03-09 Building Exterior, East Wall Left Side	DWO-061-006	Drinking Fountain Bubblers	5.02	PLMB	4.3
7 9 Auditorium/Cafeteria/Kitchen - Chesterton_03-09 Building Exterior, East Wall Right Side	DWO-061-007	Drinking Fountain Bubblers	7.23	PLMB	ND
8 9 Auditorium/Cafeteria/Kitchen - Chesterton_03-09 Kitchen, South Wall	DWO-061-008	Faucet	5.29	FLTR	ND
9 9 Auditorium/Cafeteria/Kitchen - Chesterton_03-09 Dining Rm Faculty, East Wall	DWO-061-009	Faucet	ND	INIT	
10 12 Classrooms 10-15 - Chesterton_04-12 Classroom - 10T Study Rm, South Wall	DWO-061-010	Drinking Fountain Bubblers	6.33	FLTR	ND
11 12 Classrooms 10-15 - Chesterton_04-12 Classroom - 12T Study Rm, West Wall	DWO-061-011	Drinking Fountain Bubblers	4.74	INIT	
12 12 Classrooms 10-15 - Chesterton_04-12 Classroom - 13T Study Rm, West Wall	DWO-061-012	Drinking Fountain Bubblers	4.01	INIT	
13 12 Classrooms 10-15 - Chesterton_04-12 Classroom - 15T Study Rm, North Wall	DWO-061-013	Drinking Fountain Bubblers	ND	INIT	
14 12 Classrooms 10-15 - Chesterton_04-12 Workroom, South Wall	DWO-061-014	Drinking Fountain Bubblers	2.02	INIT	
15 12 Classrooms 10-15 - Chesterton_04-12 Building Exterior, West Wall Left Side	DWO-061-015	Drinking Fountain Bubblers	NA	RMOV	
16 12 Classrooms 10-15 - Chesterton_04-12 Building Exterior, West Wall Right Side	DWO-061-016	Drinking Fountain Bubblers	NA	RMOV	
17 13 Classrooms 20-25 - Chesterton_04-13 Building Exterior, West Wall Right Side	DWO-061-017	Drinking Fountain Bubblers	6.17	FLTR	2.75



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Chesterton Elementary

Report Type: Close Out Report

Date of Report: 10/1/2018

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	13 Classrooms 20-25 - Chesterton_04-13 Classroom - 22T Study Rm, East Wall	DWO-061-018	Drinking Fountain Bubblers	4.27	INIT	
19	13 Classrooms 20-25 - Chesterton_04-13 Classroom - 23T Study Rm, South Wall	DWO-061-019	Drinking Fountain Bubblers	4.26	INIT	
20	13 Classrooms 20-25 - Chesterton_04-13 Classroom - 25T Study Rm, West Wall	DWO-061-020	Drinking Fountain Bubblers	4.99	INIT	
21	13 Classrooms 20-25 - Chesterton_04-13 Workroom, East wall	DWO-061-021	Drinking Fountain Bubblers	6.90	FLTR	0.15
22	13 Classrooms 20-25 - Chesterton_04-13 Building Exterior, South Wall Left Side	DWO-061-022	Drinking Fountain Bubblers	1.91	INIT	
23	13 Classrooms 20-25 - Chesterton_04-13 Building Exterior, South Wall Middle Left	DWO-061-023	Drinking Fountain Bubblers	2.10	INIT	
24	13 Classrooms 20-25 - Chesterton_04-13 Building Exterior, South Wall Middle Right	DWO-061-024	Drinking Fountain Bubblers	1.59	INIT	
25	13 Classrooms 20-25 - Chesterton_04-13 Building Exterior, South Side Right Side	DWO-061-025	Drinking Fountain Bubblers	<5	INIT	
26	14 Classrooms 30-35 - Chesterton_04-14 Conference Rm, North Wall	DWO-061-026	Drinking Fountain Bubblers	4.57	INIT	
27	14 Classrooms 30-35 - Chesterton_04-14 Classroom - 32T Study Rm, East Wall	DWO-061-027	Drinking Fountain Bubblers	6.14	FLTR	ND
28	14 Classrooms 30-35 - Chesterton_04-14 Classroom - 33T Study Rm, East Wall	DWO-061-028	Drinking Fountain Bubblers	5.58	FLTR	ND
29	14 Classrooms 30-35 - Chesterton_04-14 Classroom - 33T Study Rm, South Wall	DWO-061-029	Drinking Fountain Bubblers	9.40	FLTR	3.34
30	14 Classrooms 30-35 - Chesterton_04-14 Conference Rm, North Wall	DWO-061-030	Drinking Fountain Bubblers	2.05	INIT	
31	14 Classrooms 30-35 - Chesterton_04-14 Building Exterior, North Wall	DWO-061-031	Drinking Fountain Bubblers	2.45	INIT	
32	14 Classrooms 30-35 - Chesterton_04-14 Building Exterior, East Wall Middle Left	DWO-061-032	Drinking Fountain Bubblers	2.55	INIT	
33	14 Classrooms 30-35 - Chesterton_04-14 Building Exterior, East Wall Middle Left	DWO-061-033	Drinking Fountain Bubblers	<5	INIT	
34	14 Classrooms 30-35 - Chesterton_04-14 Building Exterior, East Wall Right Side	DWO-061-034	Drinking Fountain Bubblers	2.09	INIT	



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Chesterton Elementary

Report Type: Close Out Report

Date of Report: 10/1/2018

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
35 Portable B46 - Chesterton Classroom - B46, East Wall Right Side	DWO-061-035	Drinking Fountain Bubblers	1.31	INIT	
36 Portable B47 - Chesterton Classroom - B47, East Wall	DWO-061-036	Drinking Fountain Bubblers	3.12	INIT	
37 Portable B48 - Chesterton Classroom - B48, East Wall	DWO-061-037	Drinking Fountain Bubblers	2.29	INIT	
38 Portable B49 - Chesterton Classroom - B49, East Wall	DWO-061-038	Drinking Fountain Bubblers	2.21	INIT	
39 Portable B50 - Chesterton Classroom - B50, East Wall	DWO-061-039	Drinking Fountain Bubblers	<5	INIT	
40 Portable B45 - Chesterton Classroom - B45, East Wall	DWO-061-040	Drinking Fountain Bubblers	3.14	INIT	
41 Portable B44 - Chesterton Classroom - B44, East Wall	DWO-061-041	Drinking Fountain Bubblers	2.87	INIT	
42 Portable B43 - Chesterton Classroom - B43, East Wall	DWO-061-042	Drinking Fountain Bubblers	2.05	INIT	
43 Portable B42 - Chesterton Classroom - B42, East Wall	DWO-061-043	Drinking Fountain Bubblers	2.47	INIT	
44 Portable B41 - Chesterton Classroom - B41, East Wall	DWO-061-044	Drinking Fountain Bubblers	2.37	INIT	

\*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.