

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Encanto Elementary School	Report Date:	05/17/18					
Sampler:	SDUSD - Safety Office							
Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level Units = ug/L		Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB. DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable; F= Filter; R= Repaired; RM= Removed SD 1 through SD 5 = Sampled by City of San Diego						
Sample ID	Sample Location	Lead Results	Action Taken	Re-test Filter	Clearance Result	Clearance Date	Type of Fixture	
1	100 LOWER-EXTERIOR R	0.46			0.46	9/14/2017	DB	
2	100 LOWER-EXTERIOR L	0.56			0.56	9/14/2017	DB	
3A	100 LOWER-RM 103 N WALL, Left Sink	0.52			0.52	9/14/2017	DB	
3B	100 LOWER-RM 103 N WALL, Center Sink	0.60			0.60	9/14/2017	DB	
3C	100 LOWER-RM 103 N WALL, Right Sink	0.59			0.59	9/14/2017	DB	
4	100 LOWER-RM 106 W WALL	0.63			0.63	9/14/2017	DB	
5	100 LOWER-RM 107 E WALL	0.60			0.60	9/14/2017	DB	
6	100 LOWER-RM 108 W WALL	0.60			0.60	9/14/2017	DB	
7	100 LOWER-RM 109 W WALL	0.64			0.64	9/14/2017	DB	
8	100 LOWER-RM 110 N WALL	0.58			0.58	9/14/2017	DB	
9	100 LOWER-RM 111 S WALL	0.79			0.79	9/14/2017	DB	
10	100 UPPER-RM 121 SW WALL	0.16			0.16	9/14/2017	DB	
11	100 UPPER-RM 122 E WALL	0.16			0.16	9/14/2017	DB	
12	100 UPPER-RM 123 W WALL	0.16			0.16	9/14/2017	DB	
13	100 UPPER-RM 124 SP ED W WALL R	0.16			0.16	9/14/2017	DB	
14	100 UPPER-RM 124 SP ED W WALL L	0.16			0.16	9/14/2017	CF	
15	100 UPPER-RM 125 E WALL	0.16			0.16	9/14/2017	DB	
16	100 UPPER-RM 126 S wall	0.16			0.16	9/14/2017	DB	
16.1	100 UPPER- SW Corner (SD 5)	<5			<5	4/4/2017	DB	
17	200 Lower RM 201 west wall	4.30			4.30	9/14/2017	DB	
18	200 Lower RM 202 east wall	1.90			1.90	9/14/2017	DB	
19	200 Lower RM 203 west wall	3.27			3.27	9/14/2017	DB	
20	200 Lower RM 204 east wall	Removed						CF
21	200 Lower RM 205 west wall	2.00			2.00	9/14/2017	DB	
22	200 Lower RM 206 east wall	2.78			2.78	9/14/2017	DB	

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Encanto Elementary School	Report Date:	05/17/18				
Sampler:	SDUSD - Safety Office						
Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level Units = ug/L			Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB. DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable; F= Filter; R= Repaired; RM= Removed SD 1 through SD 5 = Sampled by City of San Diego				
Sample ID	Sample Location	Lead Results	Action Taken	Re-test Filter	Clearance Result	Clearance Date	Type of Fixture
23	200 Lower RM 207 east wall	1.89			1.89	9/14/2017	DB
24-25	200 Lower ext. S-Wall near RM 207 3-station L&C.	Off & No Operation					
26	200 Lower ext. S-wall near boiler Rm. R-side (SD 3)	5.73	F	2.67	2.67	1/23/2018	DB
27	200 Lower S-Wall near boiler RM. Single-Center	1.60			1.60	9/14/2017	DB
28	200 Lower ext south wall near boiler rm. Single- Left	1.66			1.66	9/14/2017	DB
29	200 Upper Rm214 east wall	2.83			2.83	9/14/2017	DB
30	200 Upper Rm 215 east wall	2.09			2.09	9/14/2017	DB
31	200 Upper Rm216 west wall	4.02			4.02	9/14/2017	DB
32	200 Upper Rm 217 east wall	3.70			3.70	9/14/2017	DB
33	200 Upper RM 218 west wall	1.76			1.76	9/14/2017	DB
34	200 Upper RM 219 east wall	2.54			2.54	9/14/2017	DB
35	200 Upper RM 220 west wall	6.39	F	ND	ND	1/23/2018	DB
36	200 Upper RM 221 east wall	11.10	F	0.21	0.21	1/24/2018	DB
37	200 Upper W-side 3-station near 224	NO SERVICE			ND	1/24/2018	DB
38	200 Upper W-side 3-station near 224 (SD 4)	9.19	R		0.24	1/24/2018	DB
38.1	200 Upper W-side 3-station near 224	NO SERVICE			ND	1/24/2018	DB
39	200 upstairs W-side single fountain-L	2.03			2.03	9/14/2017	DB
40	200 upstairs W-side single fountain-R	1.81			1.81	9/14/2017	DB
41	300 Nurse Office, South facing Bubbler, mid room	1.23			1.23	9/14/2017	DB
42	300 Teacher's Lounge, Faucet (used for coffee)	2.28			2.28	9/14/2017	CF
43	300 RM 301, West Wall, Bubbler	3.40			3.40	9/14/2017	DB
44	300 RM 302, East Wall, Bubbler	1.95			1.95	9/14/2017	DB
45	300 RM 303, West Wall, Bubbler	2.77			2.77	9/14/2017	DB
46	300 Exterior NW Wall, Triple Bubbler -L	2.42			2.42	9/14/2017	DB
47	300 Exterior NW Wall, Triple Bubbler - Center	1.50			1.50	9/14/2017	DB

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site:	Encanto Elementary School	Report Date:	05/17/18				
Sampler:	SDUSD - Safety Office						
Green shading = below District & Federal Action Levels Yellow shading = below Federal Action level/Above District Action Level Red Shading = above Federal Action Level Units = ug/L			Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB. DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet; ND=Non Detectable; F= Filter; R= Repaired; RM= Removed SD 1 through SD 5 = Sampled by City of San Diego				
Sample ID	Sample Location	Lead Results	Action Taken	Re-test Filter	Clearance Result	Clearance Date	Type of Fixture
48	300 Exterior NW Wall, Triple Bubbler - R	1.45			1.45	9/14/2017	DB
49	300 Exterior SW Wall, Single Bubbler, Left	5.95	R		ND	1/23/2018	DB
50	300 Exterior SW Wall, Single Bubbler - C	5.73	R		ND	1/23/2018	DB
50.1	300 Exterior SW Wall, Single Bubbler - R (SD 2)	< 5			< 5	4/4/2017	DB
51	300 RM 306, West Wall, Bubbler	3.02			3.02	9/14/2017	DB
52	300 RM 305, East Wall, Bubbler	2.03			2.03	9/14/2017	DB
53	300 RM 304, West Wall, Bubbler	1.69			1.69	9/14/2017	DB
54	Library, South Wall, inside small office, Bubbler	2.46			2.46	9/14/2017	DB
55	400-RM 401-N Wall	15.30	F	ND	ND	5/17/2018	DB
56	400-RM 403-N Wall	6.11	F	ND	ND	5/17/2018	DB
57	400-RM 404-N Wall	7.35	F	ND	0.28	5/17/2018	DB
58	400-RM 405-N Wall	5.01	F	ND	ND	5/17/2018	DB
59	400-RM 406-S Wall	6.70	F	ND	ND	5/17/2018	DB
60	400-RM 407-S Wall	6.09	F	ND	ND	5/17/2018	DB
61	400-RM 423-E Wall (428)	9.31	F	35.69			DB
62	400-RM 424-E Wall (429)	10.50	F	ND	ND	5/17/2018	DB
63	400-Exterior-South Wall-Left	NO SERVICE	F	22.02			DB
64	400-Exterior-South Wall-Center	NO SERVICE	F	ND	ND	5/17/2018	DB
64.1	400-Exterior-South Wall-Right (SD 1)	5.15	F	ND	ND	5/17/2018	DB
65	500 RM 501 E-Wall	22.40	F	0.73	0.73	5/17/2018	DB
66	500 RM 502 E-Wall	2.17			2.17	9/14/2017	DB
67	500 RM 503 NE Wall SP-ED	1.91			1.91	9/14/2017	DB
68	500 RM 503 NE Wall SP-ED	Removed					CF
69	500 RM 504 W-Wall	22.20	F		ND	5/17/2018	DB
70	500 RM 505 W-Wall	5.03	F		ND	5/17/2018	DB

