

May 01, 2019

Victoria Peterson
Principal
Lindbergh Elementary School
4133 Mt. Albertine Ave
San Diego, CA 92111

Subject: Lindbergh ES School Drinking Water Project Closeout

Dear Mrs. Peterson:

The following information is provided as a project closeout report for the recent drinking water lead remediation work at the Lindbergh ES campus.

As part of a district wide effort the Physical Plant Operations (PPO) staff began testing all drinking water outlets at Lindbergh Elementary School for elevated levels of lead. PPO staff first identified all drinking water outlets and tagged them with a blue label. Safety Office staff then collected water samples from each drinking water outlet and delivered the samples to a state certified laboratory for analysis. The federal EPA standard for lead in drinking water is 15 parts per billion (ppb); however, the district standard is much more stringent at 5 ppb. Drinking water fixtures that measured above the district standard were tagged "out of service" while remedial actions took place.

The attached report shows that some drinking water fixtures required remedial action in order to meet the district's strict standard of 5 ppb. Once the remedial action was completed, a re-test was conducted to confirm the remedial action was successful. All site repairs are now complete, please see the attached sampling log for more information. This project is considered closed.

Now that all drinking water outlets on the Lindbergh ES campus meet the district's lead standard of 5 ppb, your campus is now cleared from the district's daily water flushing requirement. Instead, please instruct staff to flush all drinking water outlets marked with a blue sticker for one minute in the morning of the first day of school each week, rather than every morning. Please let me know if you have any questions.

Sincerely,

Steven J. Ditto
Manager, Facilities Planning



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Lindbergh (West Campus)

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Building Exterior, Se Corner, Right Fixture, Right Bubbler	DWO-175-039	Drinking Fountain Bubbler	3.85	INIT	
2	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Building Exterior, Se Corner, Left Fixture, Left Bubbler	DWO-175-040	Drinking Fountain Bubbler	1.85	INIT	
3	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Building Exterior, Se Corner, Left Fixture, Right Bubbler	DWO-175-041	Drinking Fountain Bubbler	2.64	INIT	
4	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 21, East Wall	DWO-175-042	Drinking Fountain Bubbler	2.58	INIT	
5	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 20, West Wall	DWO-175-043	Drinking Fountain Bubbler	1.62	INIT	
6	4 Clssrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 19, East Wall	DWO-175-044	Drinking Fountain Bubbler	1.46	INIT	
7	1 Kinder Rms K01-K03 - Lindbergh Schweitzer_01-01 Classroom - K03, Bubbler At Island Sink	DWO-175-045	Drinking Fountain Bubbler	3.17	INIT	
8	1 Kinder Rms K01-K03 - Lindbergh Schweitzer_01-01 Classroom - K02, Bubbler At Island Sink	DWO-175-046	Drinking Fountain Bubbler	6.05	FLTR	ND
9	1 Kinder Rms K01-K03 - Lindbergh Schweitzer_01-01 Building Exterior, South Wall, Left Bubbler	DWO-175-047	Drinking Fountain Bubbler	2.78	INIT	
10	1 Kinder Rms K01-K03 - Lindbergh Schweitzer_01-01 Building Exterior, South Wall, Right Bubbler	DWO-175-048	Drinking Fountain Bubbler	<5	INIT	
11	1 Kinder Rms K01-K03 - Lindbergh Schweitzer_01-01 Classroom - K01, Bubbler At Island Sink	DWO-175-049	Drinking Fountain Bubbler	3.07	INIT	
12	Portable B22 - Lindbergh Schweitzer Classroom - B22, South Wall	DWO-175-050	Drinking Fountain Bubbler	5.69	FLTR	ND
13	Portable B23 - Lindbergh Schweitzer Classroom - B23, South Wall	DWO-175-051	Drinking Fountain Bubbler	6.94	FLTR	ND
14	Portable B24 - Lindbergh Schweitzer Classroom - B24A, South Wall	DWO-175-052	Drinking Fountain Bubbler			
15	Portable B25 - Lindbergh Schweitzer Classroom - B25A, Speech Room Faucet	DWO-175-053	Faucet	0.76	INIT	
16	Portable B25 - Lindbergh Schweitzer Classroom - B25A, Speech Room Bubbler	DWO-175-054	Drinking Fountain Bubbler	5.97	FLTR	ND



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Lindbergh (West Campus)

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Portable B30 - Lindbergh Schweitzer Classroom - B30A, South Wall	DWO-175-055	Drinking Fountain Bubblers	5.04	FLTR	ND
18	Portable B29 - Lindbergh Schweitzer Classroom - B29A, South Wall	DWO-175-056	Drinking Fountain Bubblers	1.61	INIT	
19	Portable B28 - Lindbergh Schweitzer Classroom - B28A, South Wall	DWO-175-057	Drinking Fountain Bubblers	2.06	INIT	
20	Portable B27 - Lindbergh Schweitzer Classroom - B27, South Wall	DWO-175-058	Drinking Fountain Bubblers	0.55	INIT	
21	Portable B26 - Lindbergh Schweitzer Classroom - B26, South Wall	DWO-175-059	Drinking Fountain Bubblers	0.71	INIT	
22	Portable Restrooms - Lindbergh Schweitzer Building Exterior, East Wall, Left Bubblers	DWO-175-060	Drinking Fountain Bubblers	0.42	INIT	
23	Portable Restrooms - Lindbergh Schweitzer Building Exterior, East Wall, Right Bubblers	DWO-175-061	Drinking Fountain Bubblers	0.44	INIT	
24	7 Library - Lindbergh Schweitzer_02-07 Building Exterior, East Wall, Left Bubblers	DWO-175-062	Drinking Fountain Bubblers	0.34	INIT	
25	7 Library - Lindbergh Schweitzer_02-07 Building Exterior, East Wall, Middle Bubblers	DWO-175-063	Drinking Fountain Bubblers	0.22	INIT	
26	7 Library - Lindbergh Schweitzer_02-07 Building Exterior, East Wall, Right Bubblers	DWO-175-064	Drinking Fountain Bubblers	0.18	INIT	
27	Portable B31 - Lindbergh Schweitzer Classroom - B31, East Wall	DWO-175-065	Drinking Fountain Bubblers	ND	INIT	
28	2 Admin - Lindbergh Schweitzer_01-02 Nurse Office - HLC1, Nw Wall	DWO-175-066	Faucet	1.82	INIT	
29	3 Audit/Kitchen/MPR - Lindbergh Schweitzer_01-03 Counseling Center, South Wall	DWO-175-067	Faucet	4.63	INIT	
30	3 Audit/Kitchen/MPR - Lindbergh Schweitzer_01-03 Building Exterior, East Wall, Left Bubblers	DWO-175-068	Drinking Fountain Bubblers	1.46	INIT	
31	3 Audit/Kitchen/MPR - Lindbergh Schweitzer_01-03 Building Exterior, East Wall, Right Bubblers	DWO-175-069	Drinking Fountain Bubblers	<5	INIT	
32	3 Audit/Kitchen/MPR - Lindbergh Schweitzer_01-03 Food Services/Kitchen - FSK1, West Wall Prep Sink	DWO-175-070	Spray Faucet	<5	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Lindbergh (West Campus)

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 04, West Wall	DWO-175-071	Drinking Fountain Bubbler	2.21	INIT	
34	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 05, East Wall	DWO-175-072	Drinking Fountain Bubbler	3.62	INIT	
35	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 06, West Wall	DWO-175-073	Drinking Fountain Bubbler	1.70	INIT	
36	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 09, West Wall	DWO-175-074	Drinking Fountain Bubbler	3.48	INIT	
37	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 08, East Wall	DWO-175-075	Drinking Fountain Bubbler	10.40	FLTR	ND
38	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 07, West Wall Faucet	DWO-175-076	Faucet	1.60	INIT	
39	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Classroom - 07, West Wall Bubbler	DWO-175-077	Drinking Fountain Bubbler	1.45	INIT	
40	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Building Exterior, West Wall, Left Bubbler	DWO-175-078	Drinking Fountain Bubbler	2.65	INIT	
41	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Building Exterior, West Wall, Middle Bubbler	DWO-175-079	Drinking Fountain Bubbler	<5	INIT	
42	6 Clssrm 4-9 - Lindbergh Schweitzer_01-06 Building Exterior, West Wall, Right Bubbler	DWO-175-080	Drinking Fountain Bubbler	1.23	INIT	
43	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 10, East Wall Faucet	DWO-175-081	Faucet	1.46	INIT	
44	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 10, East Wall Bubbler	DWO-175-082	Drinking Fountain Bubbler	1.74	INIT	
45	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 11, West Wall	DWO-175-083	Drinking Fountain Bubbler	2.22	INIT	
46	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Building Exterior, North Wall, Left Fixture, Left Bubbler	DWO-175-084	Drinking Fountain Bubbler	1.70	INIT	
47	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Building Exterior, North Wall, Left Fixture, Right Bubbler	DWO-175-085	Drinking Fountain Bubbler	0.57	INIT	
48	5 Clssrm 10-14/Supply - Lindbergh Schweitzer_01-05 Building Exterior, North Wall, Right Fixture, Left Bubbler	DWO-175-086	Drinking Fountain Bubbler	0.66	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Lindbergh (West Campus)

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
49	5 Clsrm 10-14/Supply - Lindbergh Schweitzer_01-05 Building Exterior, North Wall, Right Fixture, Right Bubbler	DWO-175-087	Drinking Fountain Bubbler	0.38	INIT	
50	5 Clsrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 14, North Wall Right Sink	DWO-175-088	Drinking Fountain Bubbler	0.85	INIT	
51	5 Clsrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 14, North Wall Right Sink	DWO-175-089	Faucet	2.58	INIT	
52	5 Clsrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 13, West Wall	DWO-175-090	Drinking Fountain Bubbler	1.29	INIT	
53	5 Clsrm 10-14/Supply - Lindbergh Schweitzer_01-05 Classroom - 12, East Wall	DWO-175-091	Drinking Fountain Bubbler	1.48	INIT	
54	4 Clsrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 15, East Wall	DWO-175-092	Drinking Fountain Bubbler	1.83	INIT	
55	4 Clsrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 16, West Wall	DWO-175-093	Drinking Fountain Bubbler	3.24	INIT	
56	4 Clsrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 17, East Wall	DWO-175-094	Drinking Fountain Bubbler	2.28	INIT	
57	4 Clsrm 15-21 - Lindbergh Schweitzer_01-04 Classroom - 18, West Wall	DWO-175-095	Drinking Fountain Bubbler	2.52	INIT	
58	4 Clsrm 15-21 - Lindbergh Schweitzer_01-04 Building Exterior, Se Corner, Right Fixture, Left Bubbler	DWO-175-096	Drinking Fountain Bubbler	1.84	INIT	
59	Portable B32 - Lindbergh Schweitzer Classroom - B32, East Wall	DWO-175-097	Drinking Fountain Bubbler	ND	INIT	
60	Portable B33 - Lindbergh Schweitzer Classroom - B33, West Wall	DWO-175-098	Drinking Fountain Bubbler	ND	INIT	
61	Portable B34 - Lindbergh Schweitzer Classroom - B34A, East Wall	DWO-175-099	Drinking Fountain Bubbler	0.47	INIT	
62	Portable B34 - Lindbergh Schweitzer Classroom - B34B, West Wall	DWO-175-100	Drinking Fountain Bubbler	0.60	INIT	
63	Portable B35 - Lindbergh Schweitzer Classroom - B35A, East Wall	DWO-175-101	Drinking Fountain Bubbler	0.38	INIT	



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Lindbergh (West Campus)

Report Type: Closeout Report

Date of Report: 05/01/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
64	Portable B35 - Lindbergh Schweitzer Classroom - B35B, West Wall	DWO-175-102	Drinking Fountain Bubbler	0.43	INIT	
65	Portable B36 - Lindbergh Schweitzer Classroom - B36, Kitchen Sink Island	DWO-175-103	Faucet	0.37	INIT	
66	Portable B38 - Lindbergh Schweitzer Classroom - B38B, East Wall	DWO-175-104	Faucet	0.33	INIT	
67	Portable B38 - Lindbergh Schweitzer Classroom - B38B, East Wall	DWO-175-105	Drinking Fountain Bubbler	0.36	INIT	
68	Portable B49 - Lindbergh Schweitzer Classroom - B49, South Wall	DWO-175-106	Drinking Fountain Bubbler	1.46	INIT	
69	Portable B48 - Lindbergh Schweitzer Classroom - B48, South Wall	DWO-175-107	Drinking Fountain Bubbler	0.50	INIT	
70	Portable B47 - Lindbergh Schweitzer Classroom - B47, South Wall	DWO-175-108	Drinking Fountain Bubbler	0.46	INIT	
71	Portable B46 - Lindbergh Schweitzer Classroom - B46, South Wall	DWO-175-109	Drinking Fountain Bubbler	41.00	FLTR	ND

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.