



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17

San Diego Unified School District

Balboa Elementary

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164531	04/06/17	05:55 AM	SAMPLE 1	3710020-ABJ-A	< 5	ug/L
W1164532	04/06/17	06:05 AM	SAMPLE 2	3710020-ABJ-B	< 5	ug/L
W1164533	04/06/17	06:10 AM	SAMPLE 3	3710020-ABJ-C	< 5	ug/L
W1164534	04/06/17	06:15 AM	SAMPLE 4	3710020-ABJ-D	< 5	ug/L
W1164535	04/06/17	06:20 AM	SAMPLE 5	3710020-ABJ-E	< 5	ug/L

- SAMPLE 1 BLDG 100, exterior between boys/girls restroom, right bubbler
SAMPLE 2 BLDG 400, inside hallway north, between girls/boys restroom, right bubbler
SAMPLE 3 BLDG 300 lower, right hallway, between boys/girls restroom, right bubbler
SAMPLE 4 BLDG 300 upstairs, between boys/girls restroom, right bubbler
SAMPLE 5 BLDG 200, next to teachers lounge, lower right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist