



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/14/17

San Diego Unified School District
Bethune K-8

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1164640	04/06/17	06:33 AM	SAMPLE 1.	3710020-ACB-A	< 5	ug/L
W1164641	04/06/17	06:29 AM	SAMPLE 2	3710020-ACB-B	< 5	ug/L
W1164642	04/06/17	06:21 AM	SAMPLE 3	3710020-ACB-C	< 5	ug/L
W1164643	04/06/17	06:15 AM	SAMPLE 4	3710020-ACB-D	< 5	ug/L
W1164644	04/06/17	06:10 AM	SAMPLE 5	3710020-ACB-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1. bldg 1, room 23, kindergarten classroom sink, bubbler at sink
- SAMPLE 2 Portable classrooms, room B-26, sink bubbler
- SAMPLE 3 Portable restroom adjacent to rooms R1-R8, floor mounted fountain near mens room, upper bubbler on dual fountain
- SAMPLE 4 BLDG 6 exterior between custodian (gear locker) and boy's restroom, left single bubbler
- SAMPLE 5 BLDG 6 exterior next to supply room, facing lunch court, left single fountain sink bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist