



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17

San Diego Unified School District

Boone Elementary School

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164073	04/04/17	06:20 AM	SAMPLE 1	3710020-AAG-A	< 5	ug/L
W1164074	04/04/17	06:13 AM	SAMPLE 2	3710020-AAG-B	< 5	ug/L
W1164075	04/04/17	06:22 AM	SAMPLE 3	3710020-AAG-C	< 5	ug/L
W1164076	04/04/17	06:28 AM	SAMPLE 4	3710020-AAG-D	< 5	ug/L
W1164077	04/04/17	06:10 AM	SAMPLE 5	3710020-AAG-E	< 5	ug/L

Sample # Sample Site

- SAMPLE 1 BLDG. 4, next to boys restroom and gardener's rm, wall mounted, right bubbler
- SAMPLE 2 BLDG. 3, btwn girls and boys' restrooms, wall mounted, right bubbler
- SAMPLE 3 BLDG. 7, 1st Floor, btwn girls and boys restroom facing amphitheater, right bubbler
- SAMPLE 4 Portable Restrooms, btwn girls and boys restrooms, facing shade shelter, wall mounted right bubbler closet to the boys restroom
- SAMPLE 5 Cafeteria, btwn cafeteria and auditorium, facing lunch arbor, wall mounted, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist