



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Cabrillo Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172996	05/20/17	05:43 AM	SAMPLE 1	3710020-BJE-A	< 5	ug/L
W1172997	05/20/17	05:49 AM	SAMPLE 2	3710020-BJE-B	< 5	ug/L
W1172998	05/20/17	05:52 AM	SAMPLE 3	3710020-BJE-C	< 5	ug/L
W1172999	05/20/17	05:56 AM	SAMPLE 4	3710020-BJE-D	8.69	ug/L
W1173000	05/20/17	06:01 AM	SAMPLE 5	3710020-BJE-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten bldg, Wall mounted exterior (East of Bldg), between Classroom K1 & Heater Room, facing playground, bubbler on right side of sink with two faucets
- SAMPLE 2 Portable Classroom B3, bubbler at sink
- SAMPLE 3 Classrooms 10-14 bldg, Wall mounted exterior (North of Bldg), between Corridor entrance and Boys RR, two single bubbler fountains, lower right fountain
- SAMPLE 4 Classrooms 15-18 bldg, Room15, bubbler at sink
- SAMPLE 5 Portable Classroom B6, buubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist