



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Cadman Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170170	05/23/17	06:01 AM	SAMPLE 1	3710020-BEB-A	< 5	ug/L
W1170171	05/23/17	06:03 AM	SAMPLE 2	3710020-BEB-B	< 5	ug/L
W1170172	05/23/17	06:06 AM	SAMPLE 3	3710020-BEB-C	< 5	ug/L
W1170173	05/23/17	06:09 AM	SAMPLE 4	3710020-BEB-D	< 5	ug/L
W1170174	05/23/17	06:11 AM	SAMPLE 5	3710020-BEB-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Inside K-1 room next to restroom, bubbler at sink
SAMPLE 2	Inside K-2 between restrooms, two sinks with bubblers, bubbler on right sink
SAMPLE 3	Classrooms 1-8 bldg, Exterior corner next to room 1, single bubbler fountain
SAMPLE 4	Classrooms 9-12 bldg, Exterior wall next to room 11, dual bubbler fountain, left bubbler
SAMPLE 5	Classrooms 1-8 bldg, Exterior wall next to room 8, dual bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist