



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/9/17

San Diego Unified School District  
Carver Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1163912	05/02/17	06:12 AM	SAMPLE 1	3710020-AAE-A	< 5	ug/L
W1163913	05/02/17	06:15 AM	SAMPLE 2	3710020-AAE-B	< 5	ug/L
W1163914	05/02/17	06:06 AM	SAMPLE 3	3710020-AAE-C	< 5	ug/L
W1163915	05/02/17	06:19 AM	SAMPLE 4	3710020-AAE-D	< 5	ug/L
W1163916	05/02/17	06:23 AM	SAMPLE 5	3710020-AAE-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten Room #1, left sink bubbler, 057-1
SAMPLE 2	Kindergarten Room 2, right sink bubbler, 057-2
SAMPLE 3	Nurses office, bubbler in main sink, 057-3
SAMPLE 4	Interior patio, mid school, left fountain, middle bubbler 057-4
SAMPLE 5	interior patio, east of grass, right fountain, middle bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist