



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17

San Diego Unified School District

Chavez Elementary

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164172	04/05/17	06:02 AM	SAMPLE 1	3710020-ABB-A	< 5	ug/L
W1164173	04/05/17	05:34 AM	SAMPLE 2	3710020-ABB-B	< 5	ug/L
W1164174	04/05/17	05:41 AM	SAMPLE 3	3710020-ABB-C	< 5	ug/L
W1164175	04/05/17	05:46 AM	SAMPLE 4	3710020-ABB-D	< 5	ug/L
W1164176	04/05/17	05:53 AM	SAMPLE 5	3710020-ABB-E	< 5	ug/L

Sample # Sample Site

- SAMPLE 1 Wall G near cafeteria, right bubbler
- SAMPLE 2 Auditorium, between mens/womens faculty rest rooms, right bubbler
- SAMPLE 3 D-102, near boys restroom D-108, right bubbler
- SAMPLE 4 upstairs D-204, between boys/girls restroom, right bubbler
- SAMPLE 5 Upstairs B Building, between restrooms B-204 and B-205, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist