



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17

San Diego Unified School District
The Children's School

| Sample ID | Sample Date | Sample Time | Source | External ID | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1173063 | 06/01/17 | 06:01 AM | SAMPLE 1 | 3710020-BJJ-A | < 5 | ug/L |
| W1173064 | 06/01/17 | 06:04 AM | SAMPLE 2 | 3710020-BJJ-B | < 5 | ug/L |
| W1173065 | 06/01/17 | 06:06 AM | SAMPLE 3 | 3710020-BJJ-C | < 5 | ug/L |
| W1173066 | 06/01/17 | 06:10 AM | SAMPLE 4 | 3710020-BJJ-D | < 5 | ug/L |
| W1173067 | 06/01/17 | 06:13 AM | SAMPLE 5 | 3710020-BJJ-E | < 5 | ug/L |

Source **Source Description**

- SAMPLE 1 Auditorium building, Exterior southeast corner of building, quadruple bubbler, far left bubbler
- SAMPLE 2 Auditorium building, Interior northeast side of building, faucet at sink
- SAMPLE 3 Classroom building (rooms9-12), Exterior east side of building, quadruple bubbler, far right bubbler
- SAMPLE 4 Classroom building, Exterior northeast corner of building, two single bubbler fountains, lower right fountain
- SAMPLE 5 Alder building, Inside room 5, faucet at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist