



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Correia Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173068	05/24/17	06:00 AM	SAMPLE 1	3710020-CAA-A	< 5	ug/L
W1173069	05/24/17	06:17 AM	SAMPLE 2	3710020-CAA-B	< 5	ug/L
W1173070	05/24/17	06:08 AM	SAMPLE 3	3710020-CAA-C	< 5	ug/L
W1173071	05/24/17	06:11 AM	SAMPLE 4	3710020-CAA-D	< 5	ug/L
W1173072	05/24/17	06:14 AM	SAMPLE 5	3710020-CAA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 400 bldg, Wall mounted exterior, between Girls and Boys RRs, single bubbler fountain by itself to the left of wall protrusion two fountain set
- SAMPLE 2 200 bldg, Wall mounted exterior on a covered breezeway, between Boys and Girls RRs, two dual bubbler fountains, left bubbler on left fountain
- SAMPLE 3 Kitchen/Cafe, Small three-compartment sink in the Back Kitchen Room, before the door of Cashier, sink faucet
- SAMPLE 4 Gym, Wall mounted exterior, next to Adapted P.E. Room, on the side of Girls' P.E., two dual bubbler fountains, left bubbler on left fountain
- SAMPLE 5 Gym, Wall mounted exterior, between Boys' PE & Girls' PE, facing ramp to Lower Field, two dual bubbler fountains, left bubbler on left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist