



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Cubberley Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168597	05/06/17	07:07 AM	SAMPLE 1	3710020-BBJ-A	< 5	ug/L
W1168598	05/06/17	07:11 AM	SAMPLE 2	3710020-BBJ-B	< 5	ug/L
W1168599	05/06/17	07:12 AM	SAMPLE 3	3710020-BBJ-C	< 5	ug/L
W1168600	05/06/17	07:14 AM	SAMPLE 4	3710020-BBJ-D	< 5	ug/L
W1168601	05/06/17	07:17 AM	SAMPLE 5	3710020-BBJ-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Kindergarten bldg., Inside K-1 in Center Island, Sink-mounted bubbler
- SAMPLE 2    Classrooms 1-6 bldg, North exterior side of building, two single-bubbler fountains, lower left fountain
- SAMPLE 3    Classrooms 7-12 bldg, North exterior side of building, two single-bubbler fountains, upper right fountain
- SAMPLE 4    Cafeteria, East exterior side of building, three single bubbler fountains right of sink/bubbler combo, far right single bubbler fountain
- SAMPLE 5    Kitchen, West interior wall of kitchen, Spray nozzle at single compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist