



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Darnall Charter**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169434	05/03/17	06:06 AM	SAMPLE 1	3710020-AHG-A	< 5	ug/L
W1169435	05/03/17	06:08 AM	SAMPLE 2	3710020-AHG-B	< 5	ug/L
W1169436	05/03/17	06:11 AM	SAMPLE 3	3710020-AHG-C	< 5	ug/L
W1169437	05/03/17	06:14 AM	SAMPLE 4	3710020-AHG-D	< 5	ug/L
W1169438	05/03/17	06:17 AM	SAMPLE 5	3710020-AHG-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    300 Building, Lunch Area outside of Men's Faculty RR, two single bubble fountains, upper right fountain
- SAMPLE 2    Bungalow Next to B-13, triple bubbler fountain, right bubbler
- SAMPLE 3    200 Building, Near room 212, dual bubbler fountain, left bubbler
- SAMPLE 4    700 Building, Corner of building, triple bubbler fountain, left bubbler
- SAMPLE 5    600 building, Near boiler room and storage room, single bubbler fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist