



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Scripps Elementary

| Sample ID | Sample Date | Sample Time | Source | External ID | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1168607 | 04/28/17 | 06:01 AM | SAMPLE 1 | 3710020-BCB-A | < 5 | ug/L |
| W1168608 | 04/28/17 | 06:03 AM | SAMPLE 2 | 3710020-BCB-B | < 5 | ug/L |
| W1168609 | 04/28/17 | 06:08 AM | SAMPLE 3 | 3710020-BCB-C | < 5 | ug/L |
| W1168610 | 04/28/17 | 06:11 AM | SAMPLE 4 | 3710020-BCB-D | < 5 | ug/L |
| W1168611 | 04/28/17 | 06:13 AM | SAMPLE 5 | 3710020-BCB-E | < 5 | ug/L |

Source **Source Description**

- SAMPLE 1 300 bldg, Down stairs hallway near custodian door 2 & girls /boys RRs, two single bubbler fountains, lower right fountain
- SAMPLE 2 300 bldg, Down stairs between 306 & RR, two single bubbler fountains, lower right fountain
- SAMPLE 3 Lunch Court yard-Restrooms, south end of lunch court, two single bubbler fountains, upper left fountain
- SAMPLE 4 300 bldg, Up Stairs, near 356, two single bubbler fountains, lower right fountain
- SAMPLE 5 300 bldg, Up Stairs, next to boys /girls RR & custodian door #3, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist