



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/17/17

San Diego Unified School District  
**Florence Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168166	04/22/17	07:07 AM	SAMPLE 1	3710020-AGJ-A	< 5	ug/L
W1168167	04/22/17	07:09 AM	SAMPLE 2	3710020-AGJ-B	< 5	ug/L
W1168168	04/22/17	07:17 AM	SAMPLE 3	3710020-AGJ-C	< 5	ug/L
W1168169	04/22/17	07:20 AM	SAMPLE 4	3710020-AGJ-D	< 5	ug/L
W1168170	04/22/17	07:13 AM	SAMPLE 5	3710020-AGJ-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Main Bldg Upper Level;Exterior west of Bldg. near boy's RR facing stairs; lower/left bubbler of 2 single fountains
- SAMPLE 2      West end Lower Level Main Bldg.; Ext.Wall mounted 3-bubbler fountain between Girls & Boys RRs; R side bubbler
- SAMPLE 3      Cafeteria/Auditorium;Wall mounted exterior (West of Bldg.), facing lunch court; Lower left of 2 single fountains
- SAMPLE 4      Bldg. 301;Wall mounted exterior betw. Boy&Girls RRs, facing Kgarten/blacktop;Upper R bubbler of 2 single fountains
- SAMPLE 5      CDC (Rms C3 & C2);Wall mounted exterior (East of Bldg.)facing Children's Center Play Area; single bubbler fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist