



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17

San Diego Unified School District

Fulton K-8

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164421	04/06/17	05:55 AM	SAMPLE 1	3710020-ABF-A	< 5	ug/L
W1164422	04/06/17	05:59 AM	SAMPLE 2	3710020-ABF-B	< 5	ug/L
W1164423	04/06/17	06:02 AM	SAMPLE 3	3710020-ABF-C	< 5	ug/L
W1164424	04/06/17	06:05 AM	SAMPLE 4	3710020-ABF-D	< 5	ug/L
W1164425	04/06/17	06:11 AM	SAMPLE 5	3710020-ABF-E	5.41	ug/L

- SAMPLE 1 Cafeteria; Prep Kitchen Sink, near door
- SAMPLE 2 Cafeteria; btwn cafeteria & auditorium; upper right bubbler
- SAMPLE 3 BLDG Rms 1-6; near speech pathologist rm, right bubbler
- SAMPLE 4 Portable Restroom; next men's restroom facing playground; front/lower bubbler
- SAMPLE 5 Kindergarten Rms K1 - K3; btwn K2&K1 facing playground; right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist