



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17


San Diego Unified School District  
**Golden Hill K-8**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170216	05/04/17	05:54 AM	SAMPLE 1	3710020-BGA-A	< 5	ug/L
W1170217	05/04/17	05:57 AM	SAMPLE 2	3710020-BGA-B	< 5	ug/L
W1170218	05/04/17	06:00 AM	SAMPLE 3	3710020-BGA-C	< 5	ug/L
W1170219	05/04/17	06:03 AM	SAMPLE 4	3710020-BGA-D	< 5	ug/L
W1170220	05/04/17	06:06 AM	SAMPLE 5	3710020-BGA-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    BLDG A, north wall of kitchen, faucet at 2 compartment sink
- SAMPLE 2    BLDG G, south side of BLDG, exterior west facing left to boys RR, triple fountain, left bubbler
- SAMPLE 3    BLDG C, south side of BLDG, exterior south wall of staff restrooms, 3 single fountains, lower right fountain
- SAMPLE 4    Newer gym, interior south wall, 2 fountains, lower left fountain
- SAMPLE 5    BLDG E, exterior north side of BLDG, 2 single fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist