

Water Quality Chemistry Services
 Lead School Testing
 Report Date: 28-Apr-2017

San Diego Unified School District
Grant K-8

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167251	4/18/2017	6:05 AM	SAMPLE 1	3710020-AGF-A	< 5	µg/L
W1167252	4/18/2017	6:00 AM	SAMPLE 2	3710020-AGF-B	< 5	µg/L
W1167253	4/18/2017	6:20 AM	SAMPLE 3	3710020-AGF-C	< 5	µg/L
W1167254	4/18/2017	6:10 AM	SAMPLE 4	3710020-AGF-D	< 5	µg/L
W1167255	4/18/2017	6:15 AM	SAMPLE 5	3710020-AGF-E	< 5	µg/L

Source **Source Description**

- SAMPLE 1 Administrative Building; Upper Level room 4 interior west wall near girl's restroom; Single wall mount bubbler
- SAMPLE 2 Administrative Building; East interior wall of Auditorium next to Food Serv. RM 221; Single wall mount bubbler
- SAMPLE 3 700 Building; Interior of classroom 11; Bubbler on the R side of the sink
- SAMPLE 4 Administrative Building; SWest exterior side of building next to PE Equip. RM 232; R bubbler of a 2 bubbler fountain
- SAMPLE 5 Kindergarten Building; Right sink inside of classroom K-1; Sink-mount bubbler on right side

DRL=State Mandated Detection Limit for Reporting (DLR)= 5 µg/L
 Action Level (AL) = 15 µg/L



Doug Campbell, Senior Chemist