



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Hage Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168383	04/25/17	06:20 AM	SAMPLE 1	3710020-BAG-A	< 5	ug/L
W1168384	04/25/17	06:13 AM	SAMPLE 2	3710020-BAG-B	< 5	ug/L
W1168385	04/25/17	06:08 AM	SAMPLE 3	3710020-BAG-C	< 5	ug/L
W1168386	04/25/17	06:05 AM	SAMPLE 4	3710020-BAG-D	< 5	ug/L
W1168387	04/25/17	06:00 AM	SAMPLE 5	3710020-BAG-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Harmonium, Inside first classroom door east wall, single bubbler fountain
- SAMPLE 2 6-12 bldg., East end between boys RR & custodial closet, two single bubbler fountains left of dual fountain, lower left fountain
- SAMPLE 3 inside classroom B-2, bubbler at sink
- SAMPLE 4 Kindergarten, inside Rm # 18, bubbler at sink
- SAMPLE 5 admin bldg. Rm. 17, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist