



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/26/17

San Diego Unified School District
Hamilton Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168052	05/16/17	06:01 AM	SAMPLE 1	3710020-AJA-A	< 5	ug/L
W1168053	05/16/17	05:59 AM	SAMPLE 2	3710020-AJA-B	< 5	ug/L
W1168054	05/16/17	06:08 AM	SAMPLE 3	3710020-AJA-C	< 5	ug/L
W1168055	05/16/17	05:53 AM	SAMPLE 4	3710020-AJA-D	< 5	ug/L
W1168056	05/16/17	06:05 AM	SAMPLE 5	3710020-AJA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Outside of PE storage on main building near asphalt play area, two single bubbler fountains, lower right fountain
- SAMPLE 2 Main Building, Facing asphalt PE/Play Area, Around the corner from Sample Point 1, two single bubbler fountains, lower left fountain
- SAMPLE 3 Main Building, Inside main office, Enter the Health Office through from desk area, Goose Neck sink faucet
- SAMPLE 4 Outside 300 Building, 1st floor, corner of building, blue-green tile, two single bubbler fountains, lower right fountain
- SAMPLE 5 Cafeteria Building, Kitchen Area, sink faucet on far sink used for food prep

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist