



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17


San Diego Unified School District
Hardy Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166868	04/15/17	07:56 AM	SAMPLE 1	3710020-AEG-A	< 5	ug/L
W1166869	04/15/17	07:52 AM	SAMPLE 2	3710020-AEG-B	< 5	ug/L
W1166870	04/15/17	08:07 AM	SAMPLE 3	3710020-AEG-C	< 5	ug/L
W1166871	04/15/17	08:00 AM	SAMPLE 4	3710020-AEG-D	< 5	ug/L
W1166872	04/15/17	08:04 AM	SAMPLE 5	3710020-AEG-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten Building, North facing side, outside play area, R side bubbler
- SAMPLE 2 Auditorium Building, outdoors on W side, R side upper bubbler
- SAMPLE 3 Administration Building; Nurse's office; sink faucet
- SAMPLE 4 Main classroom Building; S-facing wall close to RM5; Right side bubbler on triple fountain
- SAMPLE 5 Main Classroom Bdg; Triple bubbler on N-facing wall near Room #6; Bubbler on far left side

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist