



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/27/17


San Diego Unified School District  
**Hoover High**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166873	04/15/17	07:22 AM	SAMPLE 1	3710020-AFC-A	< 5	ug/L
W1166874	04/15/17	07:24 AM	SAMPLE 2	3710020-AFC-B	< 5	ug/L
W1166875	04/15/17	07:19 AM	SAMPLE 3	3710020-AFC-C	< 5	ug/L
W1166876	04/15/17	07:28 AM	SAMPLE 4	3710020-AFC-D	< 5	ug/L
W1166877	04/15/17	07:33 AM	SAMPLE 5	3710020-AFC-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Exterior East side of Cafeteria Building; Near entrance to faculty lunch room; R bubbler on triple fountain
- SAMPLE 2    Interior North side of Cafeteria building; Single Faucet on 2-compartment sink next to food service windows
- SAMPLE 3    Exterior South side of Girls Locker Room; Far right bubbler on a triple bubbler fountain
- SAMPLE 4    South side of 900 building (Southeast corner);Far right and upper bubbler of 2 separate single fountains
- SAMPLE 5    200 Building;Inside hallway next to Room 205;Lower right bubbler of 2 single fountains

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist