



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/27/17

San Diego Unified School District  
**Knox Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165252	04/12/17	06:18 AM	SAMPLE 1	3710020-ADA-A	< 5	ug/L
W1165253	04/12/17	06:15 AM	SAMPLE 2	3710020-ADA-B	< 5	ug/L
W1165254	04/12/17	06:10 AM	SAMPLE 3	3710020-ADA-C	< 5	ug/L
W1165255	04/12/17	06:22 AM	SAMPLE 4	3710020-ADA-D	< 5	ug/L
W1165256	04/12/17	06:27 AM	SAMPLE 5	3710020-ADA-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Auditorium, Exterior, next to stage door, across from luch arbor, upper right bubbler
SAMPLE 2	Kitchen, 3 compartment sink, kitchen faucet
SAMPLE 3	BLDG 3, next to supply room and girls restroom, 3 bubblers, far right
SAMPLE 4	BLDG 3, west end, next to boys RR, and pole, triple fountain, center bubbler
SAMPLE 5	Lower grass field, near restroom, freestanding dual bubbler, upper bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist