



# SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Bayview CDC

Report Type: Progress Report

Date of Report: 04/18/19

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	2 Admin/Kitchen - Bayview CDC_02-02 Common Area/Lounge - LGE1, West Wall	DWO-834-001	Faucet	3.47		
2	2 Admin/Kitchen - Bayview CDC_02-02 Food Serving, North Wall	DWO-834-003	Faucet	6.39		
3	3 Classroom 2 - Bayview CDC_02-03 Classroom - 02, East Wall	DWO-834-004	Drinking Fountain Bubblers	<5		
4	4 Classroom 3 - Bayview CDC_02-04 Classroom - 03, South Wall	DWO-834-005	Drinking Fountain Bubblers	<5		
5	5 Restrooms - Bayview CDC_02-05 Building Exterior, North Wall	DWO-834-006	Drinking Fountain Bubblers	<5		
6	5 Restrooms - Bayview CDC_02-05 Building Exterior, North Wall	DWO-834-007	Drinking Fountain Bubblers	<5		
7	Portable K03 - Bayview CDC Classroom - K03 Kinder, Island Counter	DWO-834-008	Drinking Fountain Bubblers	<5		

\*Action levels and color indication

Federal action level is above 15 ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

\*\*Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.