



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Progress Report

Date of Report: 1/25/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Nurse Office - HLC1, North Wall	DWO-113-001	Faucet	1.30		
2	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Office - MOFS, East Wall	DWO-113-002	Faucet	6.83		
3	3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Food Services/Kitchen - FSK1, East Wall	DWO-113-003	Faucet	1.64		
4	5 Classrooms 14-18 - Franklin_04-05 Building Exterior, South Wall Left Side	DWO-113-004	Bottle Filler	<5		
5	5 Classrooms 14-18 - Franklin_04-05 Building Exterior, South Wall Right Side	DWO-113-005	Bottle Filler	1.36		
6	5 Classrooms 14-18 - Franklin_04-05 Classroom - 14, West Wall	DWO-113-006	Drinking Fountain Bubblers	9.64		
7	5 Classrooms 14-18 - Franklin_04-05 Classroom - 15, West Wall	DWO-113-007	Drinking Fountain Bubblers	1.86		
8	5 Classrooms 14-18 - Franklin_04-05 Classroom - 16, West Wall	DWO-113-008	Drinking Fountain Bubblers	1.99		
9	5 Classrooms 14-18 - Franklin_04-05 Classroom - 17, West Wall	DWO-113-009	Drinking Fountain Bubblers	1.42		
10	5 Classrooms 14-18 - Franklin_04-05 Classroom - 17, North Wall	DWO-113-010	Drinking Fountain Bubblers	0.74		
11	5 Classrooms 14-18 - Franklin_04-05 Classroom - 18, North Wall	DWO-113-011	Drinking Fountain Bubblers	3.04		
12	5 Classrooms 14-18 - Franklin_04-05 Classroom - 18, West Wall	DWO-113-012	Drinking Fountain Bubblers	<5		
13	Portable B11/B12 - Franklin Classroom - B12, North Wall	DWO-113-013	Drinking Fountain Bubblers	0.80		
14	Portable B11/B12 - Franklin Classroom - B11, North Wall	DWO-113-014	Drinking Fountain Bubblers	0.71		
15	Portable B10/B11 - Franklin Classroom - B10, North Wall	DWO-113-015	Drinking Fountain Bubblers	1.74		
16	Portable B07/B08 - Franklin Classroom - B07, West Wall	DWO-113-016	Drinking Fountain Bubblers	0.83		
17	Portable B07/B08 - Franklin Classroom - B08, West Wall	DWO-113-017	Drinking Fountain Bubblers	1.14		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Progress Report

Date of Report: 1/25/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
18	Portable B08/B09 - Franklin Classroom - B09, West Wall	DWO-113-018	Drinking Fountain Bubblers	5.15		
19	7 Library - Franklin_06-07 Faculty Workroom - WRK1, South Wall	DWO-113-019	Faucet	0.61		
20	2 Classrooms 7-12 - Franklin_02-02 Common Area/Hallway - HAL1, East Wall Left Side	DWO-113-020	Drinking Fountain Bubblers	<5		
21	2 Classrooms 7-12 - Franklin_02-02 Common Area/Hallway - HAL1, East Wall Right Side	DWO-113-021	Drinking Fountain Bubblers	1.64		
22	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Left Side	DWO-113-022	Drinking Fountain Bubblers	0.97		
23	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Middle	DWO-113-023	Drinking Fountain Bubblers	1.30		
24	2 Classrooms 7-12 - Franklin_02-02 Building Exterior, South Wall Right Side	DWO-113-024	Drinking Fountain Bubblers	2.24		
25	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Left Side	DWO-113-025	Drinking Fountain Bubblers	4.46		
26	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Middle	DWO-113-026	Drinking Fountain Bubblers	1.69		
27	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, South Wall Right Side	DWO-113-027	Drinking Fountain Bubblers	1.44		
28	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Southeast End of Hall Left	DWO-113-028	Drinking Fountain Bubblers	<5		
29	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Southeast End of Hall Right	DWO-113-029	Drinking Fountain Bubblers	1.49		
30	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Northeast End of Hall Left	DWO-113-030	Drinking Fountain Bubblers	1.80		
31	1 Classrooms 1-6 - Franklin_01-01 Common Area/Hallway - HAL2, Northeast End of Hall Right	DWO-113-031	Drinking Fountain Bubblers	1.51		
32	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, East Wall Left Side	DWO-113-032	Drinking Fountain Bubblers	0.95		
33	1 Classrooms 1-6 - Franklin_01-01 Building Exterior, East Wall Right Side	DWO-113-033	Drinking Fountain Bubblers	1.50		
34	1 Classrooms 1-6 - Franklin_01-01 Faculty Workroom - WRK6, West Wall	DWO-113-034	Drinking Fountain Bubblers	2.04		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Franklin ES

Report Type: Progress Report

Date of Report: 1/25/2019

35

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
3 Admin/Auditorium/Cafeteria/Kitchen - Franklin_02-03 Office - WAIT, East Wall	DWO-113-035	Drinking Fountain Bubbler	4.43		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.