



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Taft MS

Report Type: Progress Report

Date of Report: 4/15/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
1 Admin - Taft_01-07 Nurse Health, South Wall	DWO-326-001	Faucet	1.56		
2 100 Classrooms/Library - Taft_01-08 Storage Books, South Wall	DWO-326-003	Faucet	1.00		
3 100 Classrooms/Library - Taft_01-08 Building Exterior, South Side of Bldg	DWO-326-004	Drinking Fountain Bubblers	0.85		
4 100 Classrooms/Library - Taft_01-08 Building Exterior, South Side of Bldg	DWO-326-005	Drinking Fountain Bubblers	0.30		
5 100 Classrooms/Library - Taft_01-08 Building Exterior, South Side of Bldg	DWO-326-006	Drinking Fountain Bubblers	0.20		
6 100 Classrooms/Library - Taft_01-08 Building Exterior, South Side of Bldg	DWO-326-007	Drinking Fountain Bubblers	0.20		
7 100 Classrooms/Library - Taft_01-08 Building Exterior, South Side of Bldg	DWO-326-008	Drinking Fountain Bubblers	<5		
8 600 Classrooms - Taft_01-09 Classroom - 611, West Wall	DWO-326-009	Drinking Fountain Bubblers	0.24		
9 600 Classrooms - Taft_01-09 Classroom - 604, East Wall	DWO-326-010	Drinking Fountain Bubblers	4.78		
10 600 Classrooms - Taft_01-09 Classroom - 602, East Wall	DWO-326-011	Drinking Fountain Bubblers	2.64		
11 700 Classrooms/Supply - Taft_01-10 Classroom - 702 Wood Shop, South Wall	DWO-326-012	Drinking Fountain Bubblers	2.78		
12 700 Classrooms/Supply - Taft_01-10 Multi-Media - 706, South Wall	DWO-326-013	Drinking Fountain Bubblers			
13 Portable B07 - Taft Classroom - B07, East Wall	DWO-326-014	Faucet	5.63		
14 Portable B05 - Taft Classroom - B05, East Wall	DWO-326-015	Faucet	1.75		
15 Portable B04 - Taft Classroom - B04, East Wall	DWO-326-016	Drinking Fountain Bubblers	1.68		
16 Portable B01 - Taft Classroom - B01, West Wall	DWO-326-017	Faucet	1.99		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Taft MS

Report Type: Progresss Report

Date of Report: 4/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
17	Portable B02 - Taft Classroom - B02, West Wall	DWO-326-018	Faucet	0.62		
18	Portable B03 - Taft Classroom - B03, West Wall	DWO-326-019	Faucet	1.16		
19	Portable B08 - Taft Classroom - B08, West Wall	DWO-326-020	Drinking Fountain Bubblers	0.73		
20	500 Classrooms - Taft_01-06 Building Exterior, East Wall	DWO-326-021	Drinking Fountain Bubblers	1.15		
21	500 Classrooms - Taft_01-06 Building Exterior, East Wall	DWO-326-022	Drinking Fountain Bubblers	0.74		
22	500 Classrooms - Taft_01-06 Lounge, East Wall	DWO-326-023	Faucet	0.67		
23	400 Classrooms - Taft_01-04 Storage/General - 411A, South Wall	DWO-326-024	Faucet	0.58		
24	400 Classrooms - Taft_01-04 Classroom - 408, North Wall	DWO-326-025	Drinking Fountain Bubblers	0.60		
25	Gym - Taft_01-05 Locker/Boys - LKB1, East Wall	DWO-326-026	Drinking Fountain Bubblers	0.47		
26	Gym - Taft_01-05 Building Exterior, South Side of Bldg	DWO-326-027	Drinking Fountain Bubblers	2.76		
27	Gym - Taft_01-05 Building Exterior, South Side of Bldg	DWO-326-028	Drinking Fountain Bubblers	<5		
28	Gym - Taft_01-05 Building Exterior, South Side of Bldg	DWO-326-029	Drinking Fountain Bubblers	2.00		
29	Gym - Taft_01-05 Building Exterior, South Side of Bldg	DWO-326-030	Drinking Fountain Bubblers	6.29		
30	Gym - Taft_01-05 Locker/Girls - LKG1, West Wall	DWO-326-031	Drinking Fountain Bubblers	2.15		
31	Auditorium/Cafeteria/Kitchen - Taft Building Exterior, South Side of Bldg	DWO-326-032	Drinking Fountain Bubblers	0.98		
32	Auditorium/Cafeteria/Kitchen - Taft Building Exterior, South Side of Bldg	DWO-326-033	Drinking Fountain Bubblers	1.17		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Taft MS

Report Type: Progress Report

Date of Report: 4/15/2019

Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
33 Auditorium/Cafeteria/Kitchen - Taft Building Exterior, South Side of Bldg	DWO-326-034	Drinking Fountain Bubblers	0.76		
34 Auditorium/Cafeteria/Kitchen - Taft Building Exterior, South Side of Bldg	DWO-326-035	Drinking Fountain Bubblers	<5		
35 Auditorium/Cafeteria/Kitchen - Taft Building Exterior, South Side of Bldg	DWO-326-036	Drinking Fountain Bubblers	0.80		
36 Auditorium/Cafeteria/Kitchen - Taft Kitchen - FSK1, East Wall	DWO-326-037	Faucet	<5		
37 300 Classrooms - Taft_01-01 Practice in 304 - 304B, East Wall	DWO-326-038	Drinking Fountain Bubblers	2.63		
38 300 Classrooms - Taft_01-01 Practice in 302 - 302B, West Wall	DWO-326-039	Drinking Fountain Bubblers	3.11		
39 300 Classrooms - Taft_01-01 Building Exterior, South Side of Bldg	DWO-326-040	Drinking Fountain Bubblers	3.14		
40 300 Classrooms - Taft_01-01 Building Exterior, South Side of Bldg	DWO-326-041	Drinking Fountain Bubblers	2.76		
41 300 Classrooms - Taft_01-01 Building Exterior, South Side of Bldg	DWO-326-042	Drinking Fountain Bubblers	2.77		
42 300 Classrooms - Taft_01-01 Building Exterior, South Side of Bldg	DWO-326-043	Drinking Fountain Bubblers	2.66		
43 200 Classrooms - Taft_01-02 Building Exterior, South Side of Bldg	DWO-326-044	Drinking Fountain Bubblers	0.99		
44 200 Classrooms - Taft_01-02 Building Exterior, South Side of Bldg	DWO-326-045	Drinking Fountain Bubblers	0.75		
45 200 Classrooms - Taft_01-02 Building Exterior, South Side of Bldg	DWO-326-046	Drinking Fountain Bubblers	0.95		
46 200 Classrooms - Taft_01-02 Building Exterior, South Side of Bldg	DWO-326-047	Drinking Fountain Bubblers	0.65		
47 200 Classrooms - Taft_01-02 Classroom - 212, North Wall	DWO-326-048	Drinking Fountain Bubblers	1.09		
48 200 Classrooms - Taft_01-02 Classroom - 208, North Wall	DWO-326-049	Drinking Fountain Bubblers	2.37		



SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING REPORT

Facility: Taft MS

Report Type: Progress Report

Date of Report: 4/15/2019

	Location	DWO No	Type	Initial Result*	Action Taken**	Clearance Result
49	200 Classrooms - Taft_01-02 Classroom - 206, North Wall	DWO-326-050	Drinking Fountain Bubblers	1.44		
50	200 Classrooms - Taft_01-02 Classroom - 202, North Wall	DWO-326-051	Drinking Fountain Bubblers	1.77		
51	Admin - Taft_01-07 Building Exterior, South side, left bubbler	DWO-326-052	Drinking Fountain Bubblers	22.20	RMOV	
52	Admin - Taft_01-07 Building Exterior, South side, left middle bubbler	DWO-326-053	Drinking Fountain Bubblers	9.39	RMOV	
53	Admin - Taft_01-07 Building Exterior, South side, right middle bubbler	DWO-326-054	Drinking Fountain Bubblers	7.09	RMOV	
54	Admin - Taft_01-07 Building Exterior, South side, right bubbler	DWO-326-055	Drinking Fountain Bubblers	5.89	RMOV	
55	500 Classrooms - Taft_01-06 Building Exterior, West Wall, left	DWO-326-056	Drinking Fountain Bubblers	2.88		
56	500 Classrooms - Taft_01-06 Building Exterior, West Wall, right	DWO-326-057	Drinking Fountain Bubblers	1.55		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Initial result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.