



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17

San Diego Unified School District
Lincoln High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1164177	04/08/17	07:05 AM	SAMPLE 1	3710020-ABC-A	< 5	ug/L
W1164178	04/08/17	07:31 AM	SAMPLE 2	3710020-ABC-B	< 5	ug/L
W1164179	04/08/17	07:27 AM	SAMPLE 3	3710020-ABC-C	< 5	ug/L
W1164180	04/08/17	07:15 AM	SAMPLE 4	3710020-ABC-D	< 5	ug/L
W1164181	04/08/17	07:20 AM	SAMPLE 5	3710020-ABC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 BLDG 900, behind BLDG 900 in courtyard, upper bubbler
- SAMPLE 2 BLDG 660, between 632 and 655, left bubbler
- SAMPLE 3 BLDG 1400 food service, kitchen, faucet in prep room
- SAMPLE 4 Softball and baseball field, east of softball field between stairs, lower bubbler
- SAMPLE 5 BLDG 360, between 355 and 332, back of BLDG 360, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist