



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**La Jolla High**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170063	05/12/17	06:15 AM	SAMPLE 1	3710020-BFD-A	6.34	ug/L
W1170064	05/12/17	06:10 AM	SAMPLE 2	3710020-BFD-B	10.5	ug/L
W1170065	05/12/17	06:20 AM	SAMPLE 3	3710020-BFD-C	< 5	ug/L
W1170066	05/12/17	06:05 AM	SAMPLE 4	3710020-BFD-D	< 5	ug/L
W1170067	05/12/17	06:30 AM	SAMPLE 5	3710020-BFD-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Kitchen, Inside Kitchen Left set of sinks north wall near coffee maker, faucet above two compartment sink
- SAMPLE 2      Cafeteria, Outside North around corner from service windows near door J-5B janitor, two single bubbler drinking fountains, left fountain
- SAMPLE 3      900 bldg, Outside hallway next to #901, two single bubbler drinking fountains, upper left fountain
- SAMPLE 4      300 bldg, Outside between Girls restroom & door BDF 3, two single bubbler drinking fountains, upper right fountain
- SAMPLE 5      Library Media Center, Outside at wall near entrance to Library, two single bubbler drinking fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist