



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17


San Diego Unified School District  
**Madison High**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171689	05/13/17	07:37 AM	SAMPLE 1	3710020-BGH-A	< 5	ug/L
W1171690	05/13/17	07:28 AM	SAMPLE 2	3710020-BGH-B	< 5	ug/L
W1171691	05/13/17	07:32 AM	SAMPLE 3	3710020-BGH-C	< 5	ug/L
W1171692	05/13/17	07:40 AM	SAMPLE 4	3710020-BGH-D	< 5	ug/L
W1171693	05/13/17	07:48 AM	SAMPLE 5	3710020-BGH-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Cafeteria/ Kitchen, East Wing/ East Interior Wall, two compartment sink, right faucet over right compartment
- SAMPLE 2      Boys Lockerroom/ Sports Complex-Hannon Gym, South Exterior Wall, triple bubbler fountain, right bubbler
- SAMPLE 3      Sports Complex/ Hannon Gym, North Wall at Dance Room Entrance, triple bubbler fountain, middle bubbler
- SAMPLE 4      400 BLDG, South Exterior Wall at Room 402, triple bubbler fountain, left bubbler
- SAMPLE 5      800 BLDG, North Exterior wall at Men's/ Women's RR, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist