



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Marston Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173091	05/23/17	06:19 AM	SAMPLE 1	3710020-CAD-A	< 5	ug/L
W1173092	05/23/17	06:15 AM	SAMPLE 2	3710020-CAD-B	< 5	ug/L
W1173093	05/23/17	06:11 AM	SAMPLE 3	3710020-CAD-C	< 5	ug/L
W1173094	05/23/17	06:08 AM	SAMPLE 4	3710020-CAD-D	< 5	ug/L
W1173095	05/23/17	06:05 AM	SAMPLE 5	3710020-CAD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Lockerroom 600 Bldg, South Exterior wall, triple bubbler fountain, left bubbler
- SAMPLE 2 Lockerroom 600 BLDG/ Hallway, North Facing fountain, two triple bubbler fountains, left bubbler on left fountain
- SAMPLE 3 Lockerroom 600 BLDG/ Rm 602, East Facing Exterior Wall, triple bubbler fountain, middle bubbler
- SAMPLE 4 Conservatory Terrace, Lunch Court/ East Facing; Exterior Wall Mounted System, two triple bubbler fountains, left bubbler on left fountain
- SAMPLE 5 200/ 300 Bldg, Walkway between 200 and 300 BLDG, two triple bubbler fountains, right bubbler on right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist