



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Miller Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168791	04/28/17	05:40 AM	SAMPLE 1	3710020-BCH-A	5.37	ug/L
W1168792	04/28/17	05:45 AM	SAMPLE 2	3710020-BCH-B	< 5	ug/L
W1168793	04/28/17	05:50 AM	SAMPLE 3	3710020-BCH-C	< 5	ug/L
W1168794	04/28/17	05:55 AM	SAMPLE 4	3710020-BCH-D	< 5	ug/L
W1168795	04/28/17	05:40 AM	SAMPLE 5	3710020-BCH-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Main office, nurse's area, faucet at sink
SAMPLE 2	Orange door bldg, south end, triple fountain, left bubbler
SAMPLE 3	Yellow door bldg, north end, triple fountain, left bubbler
SAMPLE 4	cafeteria, two compartment sink w/pulldown sprayer and faucet, faucet
SAMPLE 5	Green door bldg, westerly end, triple and single fountains, right bubbler on triple fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist