



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Mira Mesa High**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171674	05/10/17	06:22 AM	SAMPLE 1	3710020-BGF-A	< 5	ug/L
W1171675	05/10/17	06:19 AM	SAMPLE 2	3710020-BGF-B	< 5	ug/L
W1171676	05/10/17	06:14 AM	SAMPLE 3	3710020-BGF-C	< 5	ug/L
W1171677	05/10/17	06:07 AM	SAMPLE 4	3710020-BGF-D	< 5	ug/L
W1171678	05/10/17	06:28 AM	SAMPLE 5	3710020-BGF-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      400 bldg, Wall mounted exterior (South of Bldg) and north side of lunch court, between RRs, two single bubble fountains, upper left fountain
- SAMPLE 2      400 bldg-Kitchen, Sink in the Prep Kitchen, facing a wash-dedicated sink & walk-in fridge, faucet at single compartment sink
- SAMPLE 3      400 bldg, Culinary Classroom 420, sink in the prep kitchen (North of the Room, next to an ice machine, faucet at 2 compartment sink
- SAMPLE 4      300 bldg, Wall mounted exterior (South of Bldg), facing Library Media Center & Finance Office, 3 pairs of single bubbler fountains, right pair, lower left fountain
- SAMPLE 5      Portable Classrooms 15-11, Wall mounted exterior (West of Bldg), between Girls and Boys RRs, two single bubble fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist