



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17

San Diego Unified School District

Morse High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165137	04/07/17	06:11 AM	SAMPLE 1	3710020-ACG-A	< 5	ug/L
W1165138	04/07/17	06:18 AM	SAMPLE 2	3710020-ACG-B	< 5	ug/L
W1165139	04/07/17	06:30 AM	SAMPLE 3	3710020-ACG-C	< 5	ug/L
W1165140	04/07/17	06:24 AM	SAMPLE 4	3710020-ACG-D	< 5	ug/L
W1165141	04/07/17	06:40 AM	SAMPLE 5	3710020-ACG-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Prep kitchen sink, under window, kitchen faucet cold
- SAMPLE 2 Auditorium, exterior between boys/girls restroom, facing quad, 3 fountains, left bubbler on dual fixture
- SAMPLE 3 BLDG 300, exterior wall, next to girls restroom, facing library/innovation center, left bubbler
- SAMPLE 4 Gym, exterior wall, facing covered walkway and courtyard/culinary arts, dual fixture, right bubbler
- SAMPLE 5 CDC Room 400, classroom sink, next to Room 402, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist