



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/4/17

San Diego Unified School District  
**Normal Heights Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168368	04/29/17	07:53 AM	SAMPLE 1	3710020-BBE-A	< 5	ug/L
W1168369	04/29/17	07:55 AM	SAMPLE 2	3710020-BBE-B	< 5	ug/L
W1168370	04/29/17	07:58 AM	SAMPLE 3	3710020-BBE-C	< 5	ug/L
W1168371	04/29/17	08:00 AM	SAMPLE 4	3710020-BBE-D	< 5	ug/L
W1168372	04/29/17	08:03 AM	SAMPLE 5	3710020-BBE-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	200 bldg, : Wall mounted exterior (East of Bldg), 1st Floor (Rms 213-203), next to Unisex RR, facing courtyard, two single bubbler fountains, upper left four
SAMPLE 2	300 bldg, Rm 303, classroom sink, bubbler at sink
SAMPLE 3	400 bldg, Wall mounted exterior (South of Bldg), 1st Floor, next to RRs and walkway, facing stairs, two single bubbler fountains, upper left fountain
SAMPLE 4	500 bldg, Wall mounted exterior, 1st Floor, next to Women & Unisex Restrooms and walkway, two single bubbler fountains, upper left fountain
SAMPLE 5	Multipurpose Bldg (Auditorium/Cafeteria), Wall mounted exterior (North of Bldg), next to RRs & Lunch Arbor, two single bubbler fountains, lower right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist