



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/26/17


San Diego Unified School District
Perkins K-8

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172381	05/16/17	06:02 AM	SAMPLE 1	3710020-BHD-A	< 5	ug/L
W1172382	05/16/17	06:04 AM	SAMPLE 2	3710020-BHD-B	< 5	ug/L
W1172383	05/16/17	06:08 AM	SAMPLE 3	3710020-BHD-C	< 5	ug/L
W1172384	05/16/17	06:16 AM	SAMPLE 4	3710020-BHD-D	< 5	ug/L
W1172385	05/16/17	06:12 AM	SAMPLE 5	3710020-BHD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Multipurpose Bldg., North wall of kitchen, Faucet on a 2-compartment sink
- SAMPLE 2 600 Bldg, Exterior south wall of Room 601, triple bubbler fountain, left bubbler
- SAMPLE 3 500 Bldg, Exterior north wall of 1st floor RRs, two single bubbler fountains, lower left fountain
- SAMPLE 4 Administration Bldg, South wall of nurse's room, Faucet on a single compartment sink
- SAMPLE 5 300 Bldg, Exterior south wall, triple bubbler fountain, middle bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist