



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/12/17

San Diego Unified School District  
**Rolando Park Elementary**

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164183	04/05/17	05:33 AM	SAMPLE 1	3710020-ABD-A	< 5	ug/L
W1164184	04/05/17	05:37 AM	SAMPLE 2	3710020-ABD-B	< 5	ug/L
W1164185	04/05/17	05:40 AM	SAMPLE 3	3710020-ABD-C	< 5	ug/L
W1164186	04/05/17	05:43 AM	SAMPLE 4	3710020-ABD-D	< 5	ug/L
W1164187	04/05/17	05:48 AM	SAMPLE 5	3710020-ABD-E	< 5	ug/L

- SAMPLE 1 BLDG w/rooms 21-26, outside staff restroom, left bubbler
- SAMPLE 2 Outside cafeteria, facing playground, right bubbler
- SAMPLE 3 between student/staff restroom bldg, right bubbler
- SAMPLE 4 student/staff restroom bldg, under cover walkway, right bubbler
- SAMPLE 5 Kindergarten area, outside K-1 and K-2, single bubbler

DLR= State Mandated Detection Limit for Reporting (DL)  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist