



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17

San Diego Unified School District
San Diego CO-OP#2 North

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165270	04/08/17	06:15 AM	SAMPLE 1	3710020-AHA-A	< 5	ug/L
W1165271	04/08/17	06:40 AM	SAMPLE 2	3710020-AHA-B	< 5	ug/L
W1165272	04/08/17	06:25 AM	SAMPLE 3	3710020-AHA-C	< 5	ug/L
W1165273	04/08/17	06:30 AM	SAMPLE 4	3710020-AHA-D	< 5	ug/L
W1165274	04/08/17	06:35 AM	SAMPLE 5	3710020-AHA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 South side office, in office, bubbler at sink
- SAMPLE 2 Back of Bldg 22, under stairs, right bubbler
- SAMPLE 3 Room 16, inside, bubbler at sink
- SAMPLE 4 Room 29, inside, bubbler at sink
- SAMPLE 5 Room 22, inside, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist