



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/26/17

San Diego Unified School District  
**Sequoia Elementary**

| Sample ID | Sample Date | Sample Time | Source   | External ID   | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1172862  | 05/18/17    | 05:58 AM    | SAMPLE 1 | 3710020-BIE-A | < 5  | ug/L  |
| W1172863  | 05/18/17    | 06:03 AM    | SAMPLE 2 | 3710020-BIE-B | < 5  | ug/L  |
| W1172864  | 05/18/17    | 06:05 AM    | SAMPLE 3 | 3710020-BIE-C | < 5  | ug/L  |
| W1172865  | 05/18/17    | 06:10 AM    | SAMPLE 4 | 3710020-BIE-D | < 5  | ug/L  |
| W1172866  | 05/18/17    | 06:12 AM    | SAMPLE 5 | 3710020-BIE-E | < 5  | ug/L  |

**Source**      **Source Description**

- SAMPLE 1      Kindergarten, East exterior wall between K-1 & K-2, single bubbler fountain
- SAMPLE 2      Lunch Court, South exterior wall next to lunch court, triple bubbler fountain, middle bubbler
- SAMPLE 3      Kitchen, South interior wall, spray nozzle at two compartment sink
- SAMPLE 4      Classrooms 1-6 bldg, South exterior wall near restroom, triple bubbler fountain, left bubbler
- SAMPLE 5      Classrooms 7-12 bldg, South exterior wall next to boy's restroom, triple bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist