



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/26/17

San Diego Unified School District  
**Sessions Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172867	05/18/17	05:55 AM	SAMPLE 1	3710020-BIF-A	< 5	ug/L
W1172868	05/18/17	06:00 AM	SAMPLE 2	3710020-BIF-B	< 5	ug/L
W1172869	05/18/17	06:00 AM	SAMPLE 3	3710020-BIF-C	< 5	ug/L
W1172870	05/18/17	06:05 AM	SAMPLE 4	3710020-BIF-D	< 5	ug/L
W1172871	05/18/17	06:05 AM	SAMPLE 5	3710020-BIF-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Cafeteria, Inside Kitchen under window has red counter, Standard Kitchen faucet
- SAMPLE 2      Auditorium, Outside near Auditorium door at wall near lunch court, triple bubbler fountain, left bubbler
- SAMPLE 3      Pre-School-Kindergarten bldg, Inside # 20 at handwashing sink near restroom, two sinks, bubbler on left sink
- SAMPLE 4      Rooms 1-6 bldg, Outside North end near playground has ocean painting on wall, triple bubbler fountain, middle bubbler
- SAMPLE 5      Rooms 15-18-PSY Speech bldg, North end close to room Related Specialized Services & RRs, triple bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist