



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

San Diego Unified School District  
**Sunset View Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1173096	05/24/17	06:19 AM	SAMPLE 1	3710020-CAE-A	< 5	ug/L
W1173097	05/24/17	06:17 AM	SAMPLE 2	3710020-CAE-B	< 5	ug/L
W1173098	05/24/17	06:31 AM	SAMPLE 3	3710020-CAE-C	< 5	ug/L
W1173099	05/24/17	06:29 AM	SAMPLE 4	3710020-CAE-D	< 5	ug/L
W1173100	05/24/17	06:24 AM	SAMPLE 5	3710020-CAE-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Main Office, Wall mounted exterior (West of Bldg), next to Gate, triple bubbler fountain, middle bubbler
- SAMPLE 2    Auditorium/Cafeteria, Wall mounted exterior (East of Bldg), facing lunch arbor, two single bubbler fountains, upper left fountain
- SAMPLE 3    Portable Classrooms, Wall mounted exterior of (East of B3), facing stairs, triple bubbler fountain, middle bubbler
- SAMPLE 4    Portable Classroom/Restroom, Wall mounted exterior (South of Restroom/B6), next to shed, facing grass field, triple bubbler fountain, left bubbler
- SAMPLE 5    Kindergarten, Wall mounted exterior (East of Bldg), between Storage and Kindergarten 1, facing tables & playground, dual bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist