



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Taft Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168403	04/25/17	06:09 AM	SAMPLE 1	3710020-BBA-A	< 5	ug/L
W1168404	04/25/17	06:00 AM	SAMPLE 2	3710020-BBA-B	< 5	ug/L
W1168405	04/25/17	06:05 AM	SAMPLE 3	3710020-BBA-C	6.29	ug/L
W1168406	04/25/17	06:12 AM	SAMPLE 4	3710020-BBA-D	< 5	ug/L
W1168407	04/25/17	06:16 AM	SAMPLE 5	3710020-BBA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria Bldg, East wall of kitchen, Faucet on a 2-compartment sink
- SAMPLE 2 Cafeteria, South walkway, quadruple bubbler fountain on brick pedistal, far right bubbler
- SAMPLE 3 Gymnasium, Exterior South wall of Girl's Locker room, triple bubbler fountain, right bubbler
- SAMPLE 4 Gymnasium, Exterior South wall of Boy's Locker room, triple bubbler fountain, right bubbler
- SAMPLE 5 Library, South walkway, quadruple bubbler fountain on brick pedistal, far right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist