



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17

San Diego Unified School District
Thrive Charter

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1164824	04/07/17	06:24 AM	SAMPLE 1	3710020-ACC-A	< 5	ug/L
W1164825	04/07/17	06:28 AM	SAMPLE 2	3710020-ACC-B	< 5	ug/L
W1164826	04/07/17	06:31 AM	SAMPLE 3	3710020-ACC-C	< 5	ug/L
W1164827	04/07/17	06:34 AM	SAMPLE 4	3710020-ACC-D	< 5	ug/L
W1165275	04/08/17	09:36 AM	SAMPLE 5	3710020-ACC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 BLDG 29, outside wall of Room 29, middle bubbler on right fountain
- SAMPLE 2 Room 35, bubbler in sink
- SAMPLE 3 Room 36, bubbler in sink
- SAMPLE 4 Room 37, bubbler in sink
- SAMPLE 5 Room 25, bubbler in sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist