



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Tierrasanta Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169375	05/10/17	06:23 AM	SAMPLE 1	3710020-BDI-A	< 5	ug/L
W1169376	05/10/17	06:13 AM	SAMPLE 2	3710020-BDI-B	< 5	ug/L
W1169377	05/10/17	06:11 AM	SAMPLE 3	3710020-BDI-C	< 5	ug/L
W1169378	05/10/17	06:18 AM	SAMPLE 4	3710020-BDI-D	< 5	ug/L
W1169379	05/10/17	06:20 AM	SAMPLE 5	3710020-BDI-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      East facing wall next to Multipurpose Room and Boys RR, two single-bubbler fountains, lower left fountain
- SAMPLE 2      Lunch Arbor and Kitchen Area, On South facing wall of kitchen exterior, triple bubbler fountain, center bubbler
- SAMPLE 3      Kitchen, single compartment prep sink, faucet above sink
- SAMPLE 4      Southwest class building, exterior, Southwest corner of campus, triple bubbler fountain, left bubbler
- SAMPLE 5      Southeast class room building, exterior, South facing wall of building, double bubbler fountain left of single bubbler fountain. right bubbler on double fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist