



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
Toler Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172909	05/19/17	06:05 AM	SAMPLE 1	3710020-BIJ-A	< 5	ug/L
W1172910	05/19/17	06:09 AM	SAMPLE 2	3710020-BIJ-B	< 5	ug/L
W1172911	05/19/17	06:12 AM	SAMPLE 3	3710020-BIJ-C	< 5	ug/L
W1172912	05/19/17	06:15 AM	SAMPLE 4	3710020-BIJ-D	< 5	ug/L
W1172913	05/19/17	06:18 AM	SAMPLE 5	3710020-BIJ-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten bldg, South exterior wall between classrooms A and B, two single bubbler fountains, lower left bubbler
- SAMPLE 2 Classrooms 1-6 (bldg. 1), North exterior wall next to boy's RR, Close to room 4, triple bubbler fountain, center bubbler
- SAMPLE 3 Kitchen, North interior wall, faucet above two compartment sink
- SAMPLE 4 Classrooms 7-12 (bldg. 2), South exterior wall next to lunch court, three single bubbler fountains, upper right fountain
- SAMPLE 5 Restroom Bungalow, Exterior wall between boy & girl's restroom, two single bubbler fountains, upper left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist